
12 x 16 FT

0000000**JFG-005** 000000000






At least need 3people work together


REQUIRED TOOLS




































































	Box A		Box C		Box D	
	Part #	Qty	Part #	Qty	Part#	Qty
	A5	4	B2	2	F8	4
	E3	6	В3	2	F9	4
İ	Y5	4	D5	4	F10	4
İ	Y6	4	Y	2	F11	4
	Y7	4	Н	4	F12	4
	Y8	4	H1	4	F13	4
	Z	2	L1	1	F14	6
	Z1	4	M1	1		
	Z2	4	K	4		
			K1	2		
İ			K2	2		
			X	6		
			Р	4		
			U	128		
Box B			J2	4		
	Part #	Qty	V	4		
	C2	2	N	4		
	C3	2	N1	6		
	D3	4	S1	4		
			T1	4		
			1-9	1		