ProAiir INK Instructions

Application

- Shake well before use.
- No thinning needed. ProAiir is ready to spray right out of the bottle.
- Apply on clean skin, free of sunscreens or lotions.
- Airbrush with pressure at 15-20 PSI. In extreme heat, increase to 20-25 PSI.
- Apply in thin layers to avoid cracking.
- Apply powder between layers and to finished design to alleviate tack.
- For thinner consistency add ProLong. It will not affect color opacity or pigmentation.

Removal / Cleaning

- Remove from skin with 91% alcohol or baby oil
- Clean your airbrushes with 91% alcohol or denatured alcohol. NO WATER!

Longevity Factors

- All skin types are different. One person's design may last longer than another simply because their skin exfoliates faster or slower.
- Placement of a tattoo affects the longevity. High sweat and friction areas like the neck, inside
 of arm, and lower back will remove faster than a design placed on the leg, shoulder, or
 outside of the arm.
- If a client has been consuming alcohol, their designs will come off faster because the alcohol will sweat through the pores, causing the removal of the makeup.
- If you want your designs to last a little longer, apply a thin layer of ProLong to your art.

Special Notes

- Separation of pigments is normal. Pigment will settle to the bottom of the bottle over time. Simply shake until blended again.
- Do not apply on sunburnt skin, open wounds, or sores.
- Use plastic bottles for best results (or just the ProAiir bottles). Glass bottles attract hear, curing faster evaporation of product causing it to get thick.
- DO NOT mix ProAiir with water. Make sure to empty the water trap after each gig if you are using a compressor.
- Clean stencils by soaking in alcohol and gently brush away the makeup with any soft bristled brush.

For tutorials, check out the ProAiir YouTube channel https://www.youtube.com/@proaiirmakeup