


## CHAININSTALLATION(OptionOne)



Step 1. Insert a chain on each hook and insert hooks into the installation holes




Step 2. Attach the chains to the ceiling and adjust till balanced and secured



Step 3. Take wires from the shielded cables, connect AC wires and Dimming wires (if needed)




Step 4. Wrap the wires with metal materials




Step 5. Optional seamless infinite splicing


## CHAININSTALLATION(OptionTwo)




Step 1. Snap buckles into the lamp body




Step 2. Attach the hooks at the slotted holes of buckles




Step 3. Hook buckles with pendant cord and suspend the light to the desired height




Step 4. Take wires from the terminal caps, connect AC wires and Dimming wires (if needed)



Step 5. Insert the terminal blocks and wires into the strip




Step 6. Insert the wire terminal joints to the wire entry




Step 7. Optional seamless infinite splicing


## SURFACEMOUNTED INSTALLATION




Step 1. Fix the buckles in parallel by screws with distance between each buckle



Step 2. Take wires from the terminal caps, connect AC wires and Dimming wires (if needed)



Step 3. Secure the strip with buckles



Step 4. Installation is completed