
## ARMANOV


## OAL Checker for Armanov Case Gauge

1
Put the OAL
Checker on a
flat surface.
Position a filled
up case gauge
precisely on
top of the OAL
Checker.



Cases will rise about the level of case gauge. You can easily spot rounds with bullets seated too deep or not

enough.





Armanov d.o.o. Brezovce 9 1236 Trzin, Slovenija Tel: +386 30 467 000 armanov.com