

# EASISOLV 110

## SOLVENT REMOVER

EasiSolv 110 Solvent Cleaner is a quick-drying cleaner formulated to effectively remove printing inks from screen printing mesh, squeegees, flood bars, presses, pad printing tools, rotary screens, and more. The combination of components is designed to solubilize and remove all types of ink and minimize staining in the printing mesh.

<b>Appearance:</b>	Clear, light yellow
<b>Odor:</b>	Ether-like
<b>Ph:</b>	Neutral
<b>Flash Point:</b>	48°C / 118°F
<b>Specific Gravity:</b>	0.95 @ 20°C / 68°F
<b>Weight/gl:</b>	Not Applicable
<b>VOCs:</b>	950 grams/liter
<b>Dot Shipping:</b>	Non-hazardous

<b>Quart</b>	110-1 QT
<b>Gallon</b>	110-1 GL
<b>5 Gallon pail</b>	110-5 GL
<b>55 Gallon Drum</b>	110-55 GL

### STORAGE REQUIREMENTS

Keep the container tightly closed. Store in a dry, cool and well ventilated place away from incompatible materials such as oxidizing agents and acids.

### PRODUCT FEATURES

- Low flash point
- Quick evaporation
- Good adhesive remover
- Non-hazardous
- Low to no odor

### APPLICATION/USE

Scrape excess ink from the screen. Apply EasiSolv 110 by squirt bottle, pneumatic sprayer, or rag to the (well) ink side of the screen. Thoroughly agitate ink with a rag or a scrubber, then wipe up all the dissolved ink with a shop rag on both sides. Reapply if necessary and follow with a dry rag.

### COMPATIBLE INK TYPES

- Plastisol
- Industrial
- Waterbased