PHOENIX SMART PRODUCT PROFILE


TOPDON®



PHOENIX SMART

The Phoenix Smart® is part of TOPDON's new generation of intelligent diagnostic tools. Equipped with quad-core processors and a 10.1" HD touch screen, this tool allows you to diagnose fault codes with one click. Its 12600mAh battery can work all day without fear of losing power. The Phoenix Smart also supports Cloud-Based Programming for over 13 car brands and includes 2 years of free software upgrades.

Combined with the MDCI Pro, this scanner gives you unprecedented coverage, intelligent diagnoses, and a wide array of maintenance functions.



TOPDON®

PHOENIX SMART SPCES

Display	LCD 10.1" touchscreen, 1280*800	
CPU	4-Core Processor, 2.0 GHz, Android 10.0	
RAM	4G	
ROM	128G	
Battery	12600 mAh / 3.8V	
Operating Voltage	9~18V	
Storage Temperature	-20°C to 60°C (-4°F to 140°F)	
Working Temperature	0°C to 50°C (32°F to 122°F)	
Dimensions	278 x 191 x 48mm (10.94 x 7.52 x 1.89'')	
Package Size	468 x 320 x 143mm (18.43 x 12.60 x 5.63")	
Multilingual Support	English, German, Spanish, French, Italian, Japanese, Portuguese, Russian, Polish, Turkish, Dutch, Hungarian, Chinese(Traditional), Korean, Finnish	

PHOENIX MDCI PRO SPECS

CPU	Cortex-A7 + Cortex-M7, Dual Processor
Operating System	Linux
RAM	256M
ROM	8G
Display	TFT, 3.97", 320x480Pixels
Wi-Fi	2.4GHz/5GHz, Dual Band
Working Temperature	0°C~50°C (32°F~122°F)
Operating Voltage	DC 9~36 V
Dimensions	196 x 135 x 42.8 mm (7.72 x 5.31 x 1.69")
New Protocols Supported	J2534, CAN FD, DOIP, D-PDU, RP1210



PROGRAMMING FUNCTIONS
AND ONLINE CODING

The Phoenix Smart includes Online Coding Functions for Audi, BMW, Porsche, and other vehicle manufacturers.

It supports Cloud Based Programming functions for 13+ car brands, such as Mercedes-Benz, BMW, VW(Audi/Skoda/Seat), Porsche, Land Rover/Jaguar, Nissan, Subaru, Renault, Hyundai, and many more!



THE PHOENIX MDCI PROHAS YOU COVERED!

12534

TOPDON's Phoenix Smart comes with the Phoenix MDCI Pro, a VCI that supports J2534, DoIP, CanFD, D-PDU, and RP1210 protocols.

This MDCI Pro's unparalleled coverage allows you to offer OE-level services to newer and more modern vehicles. With the Phoenix MDCI Pro, you will never be forced to outsource!



TOPDON®

STEP-BY-STEP GUIDED PROCEDURES

streamlines the repair

and SEAT vehicles.




TOPDON®


VIEW ALL FAULT CODES ON ONE SCREEN!

The Phoenix Smart Utilizes Topology mapping, displaying the entire vehicle system.

Raw data is transformed into clear graphics, so technicians can see the entire status of the car system and get right to the vehicle's issues.








TOPDON < ADAS 6首 ADAS Calibration ADAS Vehicle Coverage 0 **Phoenix** Smart

Offer in-demand services to your customers with the Phoenix Smart. Pair the Phoenix Smart with TOPDON's Phoenix ADAS Mobile Package to calibrate intricate driving assistance functions.

As ADAS software becomes more common in modern vehicles, the demand for ADAS recalibration will only grow. Meet this growing demand with confidence.

ADAS COMPATIBILITY





PHOENIX SMART FUNCTIONS

The Phoenix Smart offers Full System Diagnostics for over 200 Vehicle Makes

Essential Functions

- ECU Lookup
- Read Fault Code
- Clear Fault Code
- Read Data Streams
- Actuation Test

Special Features

- Cloud-Based Programming
- Online Coding
- 34 Maintenance Services
- VAG Guided Function
 And More


Expanded Functions

- ADAS Compatibility
- Battery Tester Compatibility

Others

- FCA Secure Gateway Access
- Topology Mapping
- Auto Vin
- 10 OBD Functions
- Auto Scan
- Feedback
- Remote Assistance
- One-Tap Upgrades
- Save and Share Report, Print Report Via PC

ESSENTIAL FUNCTIONS



ECU Lookup


Read Fault Code

Clear Fault Code

Read Data Streams

Actuation Test

SPECIAL FEATURES



Cloud-Based Programming

34 Maintenance Services

And More

Online Coding

VAG Guided Function

CLOUD-BASED PROGRAMMING Models supporting cloud-based programming


BRANDS	YEAR
Mercedes-Benz	Until 2020
BMW	Until Feb. 2021
AUDI	Until 2021
VW/SKODA/SEAT	Until 2021
Porsche	Until 2020
Jaguar/Land Rover	Until 2017
Nissan	Until 2020
Subaru	Until 2020
Renault	Until 2021 (Part of modes Supported)
Hyundai	Until 2018 (Part of modes Supported)

ONLINE CODING


TOPDON®

Online Coding Available on the following Vehicles

- Benz
- BMW
- Volkswagen
- Audi
- Skoda
- Seat
- Porsche
- Land Rover
- Jaguar
- Nissan
- Subaru
- Renault



34 MAINTENANCE SERVICES



Oil Reset (53 brands)

EBP Reset (41 brands)

DPF (39 brands)

IMMOBILIZER (45 brands)

Suspension Reset (11 brands)

AFS Headlamp Reset (9 brands)

Gear Learning (3 brands)

Throttle Adaptation (37 brands)

ADBLUE Reset (8 brands)

EGR Reset (7 brands)

NOx Sensor Reset (8 brands)

Seats Calibration (18 brands)

Reset AIRBAG (4 brands)

TYPE Reset (5 brands)

Power Balance (9 brands)

AC System Relearn (10 brands)

STOP/START (5 brands)

SAS Reset (44 brands)

BMS Reset (31 brands)

ABS Bleeding (34 brands)

Sunroof Reset (4 brands)

Gearbox Reset (8 brands)

Injector Coding (41 brands)

TPMS Reset (38 brands)

A/F Reset (5 brands)

Coolant Bleed (5 brands)

Language Change (7 brands)

Odometer Calibration (9 brands)

Motor Angle Calibration (5 brands)

Transport mode (13 brands)

Windows Calibration (15 brands)

Gas Particulate Filter Regeneration (14 brands)

High Voltate Battery Diagnostics (7 brands)

Intelligent Cruise Control System

VAG GUIDED FUNCTION

Guided procedures and functions streamlines the repair process. Follow the prompts for easy and convenient operation, suitable for VW, Audi, Skoda and SEAT vehicles.



EXPANDED FUNCTIONS



ADAS Compatibility

Note: TOPDON's Phoenix Mobile ADAS and target packages need to be purchased separately to perform the ADAS calibration.



Battery Tester Compatibility

Note: Battery Tester functionality is only available if you purchase a TOPDON® BTMobile $ProS^{TM}$.

OTHER FUNCTIONS

1. OBD Functions

Support 10 kinds of OBD Modes

2. Auto Vin

The Phoenix Smart automatically uses the right diagnostic software after identifying the vehicle through its VIN.

3. Auto Scan

Automatically Scan All the On-Board Systems.

4. Tool Feedback

Feedback can provide better after-sales service to customers.

5. One-Tap Upgrades

Updating is easy and convenient.

Connect to WIFI. After selecting all software, tap Update to upgrade all software with one tap.

- 6. Save and Share Reports
- 7. FCA Secure Gateway Access
- 8. Topology Mapping

WHAT'S INTHE BOX3

TOPDON®

- 1* Phoenix Smart
- 1* Phoenix MDCI Pro(VCI Dongle)
- 1* OBDI Adapter BOX Transfer Line
- 1* OBDII Extension Cable
- 1* Cigarette Lighter Cable
- 1* Type-C to USB Cable
- 1* Battery Clamps/Cable Set
- 1* User Manual
- 1* Password Envelope
- 10* Non-16pin Adaptor Cable Kit (NN-14+16, BZ-38, T. TA-22, G/V-12, B-20, CR-6, HA-3, M/H-12+16, FT-3)
- 4* Fuse (φ5*20mm)
- 2* Fuse (φ6*30mm)
- 1* Type A to B Cable





AL500B,BT300P,BT100

Phoenix Plus







SPECIFICATIONS

HARDWARE			
CPU	4-Core 2.0GHz	MT6761 Core 4, 2.0GHZ	MT6761 Core 4, 2.0GHZ
RAM	4G	4G	4G
ROM	64G	64G	128G
Battery Capacity	12600mAh, 3.8v	12600mAh, 3.8v	12600mAh, 3.8v
Android Version	Android 10.0	Android 10.0	Android 10.0
Screen Size	10.1 inch	10.1 inch	10.1 inch
Screen Resolution	1280 x 800 pixels	1280 x 800 pixels	1280 x 800 pixels
Wi-Fi	2.4 GHz	2.4 GHz	2.4 GHz
Camera	Rear8.0 mp	Rear8.0 mp	Rear8.0 mp
Weight	1.5kg (3.31 lb)	1.567 kg(3.45 lb)	1.567 kg(3.45 lb)
SOFTWARE			
Cloud-Based Programming	X	6 Brands (Audi, Benz, VW, BMW, SKODA, SEAT)	13 Brands(Benz, BMW, Audi, VW, SKODA, SEAT, Porche, Jaguar, Land Rover,Nissan, Subaru, Renault, Hyundai)
	X		SEAT, Porche, Jaguar, Land Rover, Nissan,
Cloud-Based Programming	X √ VCI/Bluetooth	BMW, SKODA, SEAT)	SEAT, Porche, Jaguar, Land Rover, Nissan, Subaru, Renault, Hyundai)
Cloud-Based Programming Remote Desk	√	BMW, SKODA, SEAT) √	SEAT, Porche, Jaguar, Land Rover,Nissan, Subaru, Renault, Hyundai) √
Cloud-Based Programming Remote Desk Communication	√	BMW, SKODA, SEAT) √	SEAT, Porche, Jaguar, Land Rover,Nissan, Subaru, Renault, Hyundai) √
Cloud-Based Programming Remote Desk Communication ADAS	√ VCI/Bluetooth √ FCA Official	BMW, SKODA, SEAT) VCI/Bluetooth FCA Official	SEAT, Porche, Jaguar, Land Rover, Nissan, Subaru, Renault, Hyundai) VCI/Bluetooth FCA Official
Cloud-Based Programming Remote Desk Communication ADAS FCA Secure Gateway	√ VCI/Bluetooth √ FCA Official	BMW, SKODA, SEAT) VCI/Bluetooth FCA Official	SEAT, Porche, Jaguar, Land Rover, Nissan, Subaru, Renault, Hyundai) VCI/Bluetooth FCA Official
Cloud-Based Programming Remote Desk Communication ADAS FCA Secure Gateway Auto VIN	√ VCI/Bluetooth √ FCA Official	BMW, SKODA, SEAT) VCI/Bluetooth FCA Official	SEAT, Porche, Jaguar, Land Rover, Nissan, Subaru, Renault, Hyundai) VCI/Bluetooth FCA Official
Cloud-Based Programming Remote Desk Communication ADAS FCA Secure Gateway Auto VIN Full-System Diagnostic Daily Maintenance Functions (Only the Commonly Used Special Functions, such as: EPB OLS, BMS, DPF, SAS,	√ VCI/Bluetooth √ FCA Official Account Subs Fee √	BMW, SKODA, SEAT) VCI/Bluetooth V FCA Official Account Subs Fee V	SEAT, Porche, Jaguar, Land Rover, Nissan, Subaru, Renault, Hyundai) V VCI/Bluetooth FCA Official Account Subs Fee V

Software Languages

Bus Protocols: DoIP/CAN FD

The standing of the standing o

X

15 Languages
English, German, Spanish,
French, Italian, Japanese,
Portuguese, Russian, Polish,
Turkish, Dutch, Hungarian,
Chinese (Traditional),
Korean, Finnish

Only CAN FD Supported

15 Languages
English, German, Spanish,
French, Italian, Japanese,
Portuguese, Russian, Polish,
Turkish, Dutch, Hungarian,
Chinese (Traditional),
Korean, Finnish

23

FAQs

• Q Why Can't I turn on the tablet after it was fully charged?

▲ Possible cause:

The tablet has been inactive for too long, and the battery was drained.

• How to fix it:

Charge your scanner for over 2 hours before turning it on.

• If problems persist:

Please contact your dealer or TOPDON's technical support for timely assistance.

O Why can't I register my tool?

• Possible cause: Verify if: 1) The tablet isn't connected to a network; 2) Your email address may have been registered already; or 3) There is no verification code in the email box (or spam folder).

• How to fix it:

Make sure 1) your network is stable; 2) use another valid email address; 3) check if the email address is valid, and resent the code.

• If problems persist: It could be due to server maintenance. Please try again later.

Why can't I log in?

Δ • Possible cause:

The tablet isn't connected to a network, or the username/password is incorrect.

• How to fix it:

Make sure your network is stable. Then: 1) check the username and password; 2) contact TOPDON after-sales support to get the username and password.

• If problems persist:

Please contact your dealer or TOPDON's after-sale service for timely support.

Why can't I activate the equipment?

Δ • Possible cause:

The tablet isn't connected to a network; the serial number and activation code are incorrect; the activation code is invalid; the configuration is empty.

• How to fix it:

Make sure your network is stable. Then: 1) check if the serial number and activation code are correct (The Serial Number is 12 Digits. The Activation Code is 8 Digits).

• If problems persist:

Please contact your dealer or TOPDON's after-sale service for timely support.

O Why isn't the tablet activated while updating?

Δ • Possible cause:

The Phoenix MDCI Pro may not be activated in the registration process.

• How to fix it:

Activate the Phoenix MDCI Pro as follows: Tap "User Info" -> "Activate MDCI Pro " -> Input the correct serial number and activation code -> "Activate".

There is no power in the Phoenix MDCI Pro after connecting to the vehicle's DLC port?

Δ • Possible cause:

A Poor connection with the Phoenix MDCI Pro, the vehicle's DLC Port, low battery voltage, or damage to the Phoenix MDCI.

• How to fix it:

Pull out the Phoenix MDCI Pro and plug it in again. Then: 1) recharge the vehicle's battery; 2) replace the battery if it is damaged.

• If problems persist:
It could be due to server maintenance. Please try again later.

The tablet cannot establish a connection with the Phoenix MDCI Pro.

• Possible cause:

Poor contact to the Phoenix MDCI Pro, or the firmware is damaged.

• How to fix it:

1) Pull out the Phoenix MDCI Pro and then plug it in again; 2) Perform the Phoenix MDCI Pro Bluetooth pairing again. 3) Enter the settings and tap "Fix Connector Firmware/System" to fix the firmware.

O Can I use other chargers to charge the tablet?

• No, please use the original charger provided by TOPDON. Any damage and/or repair costs caused by using an improper battery charger will not be TOPDON's responsibility to refund or replace.

- O How can I save battery power?
- Switch off the screen while the tablet is inactive, set a short standby time, or reduce the brightness of the screen.
- O Are there non-standard OBDII adapters in the box?
- A Yes.
- The downloaded diagnostic software is inconsistent with the serial number. What should I do?
- Selected the wrong Phoenix MDCI Pro.
 Enter the "User Info" -> "MDCI" -> select the right Phoenix MDCI Pro.

The Scanner Failed to get access to the vehicle's ECU system. What should I do?

A • Please confirm the following cases:

1) Whether the system is available in the vehicle. 2) Whether the Phoenix MDCI is correctly connected. 3) Whether the ignition switch is ON.

O The Phoenix MDCI Pro is missing. What should I do?

• Please contact your dealer or TOPDON's after-sale service for timely support.

CONTACT US FOR MORE DETAILS

TOPDON®

www.topdon.com
sales@topdon.com
support@topdon.com
Social Media: @topdonofficial

+86-755-21612590 (Global HQ)

+1-833-629-4832 (North America)

CHINA TOPDON HQ

Unit 2005 20/F,No,3040 xinghai Avenue, Qianhai Shimao Tower, Qianhai Shenzhen-Hongkong Cooperation Zone,Shenzhen, PR, China 518000

USA TOPDON HQ

400 Commons Way, Suite A Rockaway, NJ 07856

