





### BarriAire Gold Face Mask

Style No: 3199471-3 | Style No: 3199471-4



### BarriAire Gold Face Mask

Style No: 3199471-3 | Style No: 3199471-4



#### Warranty Information:

Your protective face mask is warranted by the manufacturer to be free from defects in material and workmanship. This warranty does not cover normal wear or unusual exposures. This warranty is in lieu of all other warranties, express or implied, including but not limited to, implied warranties of marketability and/or fitness for a particular purpose. The manufacturer shall not be liable for incidental or consequential damages.

#### Warranty Information:

Your protective face mask is warranted by the manufacturer to be free from defects in material and workmanship. This warranty does not cover normal wear or unusual exposures. This warranty is in lieu of all other warranties, express or implied, including but not limited to, implied warranties of marketability and/or fitness for a particular purpose. The manufacturer shall not be liable for incidental or consequential damages.



PGI, Inc. Corporate Office  
550 Commercial Ave.  
Green Lake, WI 54941  
Email: mail@pgi-inc.com  
Phone: 800.558.8292

PGI Safety Limited  
Unit 5, Albert Edward House  
The Pavilions, Preston PR2 2YB  
Email: info@pgi-safety.com  
Phone: +44(0)1772 842115



PGI, Inc. Corporate Office  
550 Commercial Ave.  
Green Lake, WI 54941  
Email: mail@pgi-inc.com  
Phone: 800.558.8292

PGI Safety Limited  
Unit 5, Albert Edward House  
The Pavilions, Preston PR2 2YB  
Email: info@pgi-safety.com  
Phone: +44(0)1772 842115

## **CLEANING AND MAINTENANCE:**

- Clean your face mask as soon as possible after an incident where it has been soiled or exposed to blood or body fluids, tars, fuels, resins, paints, acids, by-products of combustion or other hazardous materials. Do not wear your face mask until it has been properly cleaned. If face mask cannot be properly cleaned, you must retire and dispose.
- Face mask should be washed with mild detergent in warm water not to exceed 105°F.
- Use a liquid detergent such as Tide versus a powder detergent to minimize pilling.
  - Do not use chlorine bleach or detergents containing chlorine bleach. Chlorine bleach will compromise the protective qualities provided by the fabrics used in manufacturing.
- Face masks should be laundered with like products, i.e. other flame-resistant knits such as other FR face masks, hoods, knit FR shirt, etc.
- Particulate protective gear should be washed separately from cotton and lint producing fabrics.
- To minimize fabric abrasion, hook should be attached securely to loop before laundering.
- Do not wring or squeeze face mask to remove excess water.
- Dry using “low heat” or “gentle cycles”. You may also shape and lay flat in a dry, cool shaded location to dry.
- Do not commercially dry clean!
- Before and after every use, your face mask should be inspected. All damaged face masks must be retired and disposed. Any physical change in any component should be immediately referred to personnel to determine if you face mask’s protective qualities have been compromised.
- In the event of either questionable appearance or characteristics, caution should prevail and the face mask should be replaced.

## **MAINTENANCE AND REPAIRS:**

- Repair is generally not practical or recommended considering the cost of a new face mask. If repair is desired, refer to the manufacturer or to a facility capable of making repairs consistent with the original manufacturer. PGI does not warranty any face mask in which repairs have been made without the specific written permission or inclusion of PGI, Inc.

## **CLEANING AND MAINTENANCE:**

- Clean your face mask as soon as possible after an incident where it has been soiled or exposed to blood or body fluids, tars, fuels, resins, paints, acids, by-products of combustion or other hazardous materials. Do not wear your face mask until it has been properly cleaned. If face mask cannot be properly cleaned, you must retire and dispose.
- Face mask should be washed with mild detergent in warm water not to exceed 105°F.
- Use a liquid detergent such as Tide versus a powder detergent to minimize pilling.
  - Do not use chlorine bleach or detergents containing chlorine bleach. Chlorine bleach will compromise the protective qualities provided by the fabrics used in manufacturing.
- Face masks should be laundered with like products, i.e. other flame-resistant knits such as other FR face masks, hoods, knit FR shirt, etc.
- Particulate protective gear should be washed separately from cotton and lint producing fabrics.
- To minimize fabric abrasion, hook should be attached securely to loop before laundering.
- Do not wring or squeeze face mask to remove excess water.
- Dry using “low heat” or “gentle cycles”. You may also shape and lay flat in a dry, cool shaded location to dry.
- Do not commercially dry clean!
- Before and after every use, your face mask should be inspected. All damaged face masks must be retired and disposed. Any physical change in any component should be immediately referred to personnel to determine if you face mask’s protective qualities have been compromised.
- In the event of either questionable appearance or characteristics, caution should prevail and the face mask should be replaced.

## **MAINTENANCE AND REPAIRS:**

- Repair is generally not practical or recommended considering the cost of a new face mask. If repair is desired, refer to the manufacturer or to a facility capable of making repairs consistent with the original manufacturer. PGI does not warranty any face mask in which repairs have been made without the specific written permission or inclusion of PGI, Inc.