



# BUG-BEAM™ INSTALLATION



## Tools You Will Need:


#2 Phillips Screwdriver - Aluminum Foil & Tape - Allen Wrench ( In Package )



\*Combined Explanatory, Hazard Warning, Certification, & Manufactures Identification Label

## INSTALLATION


- 1 Using #2 Phillips head screwdriver loosen out adapter screw half inch



- 2 Slide laser out from adapter ring




- 3 Slip adapter ring on BUG-A-SALT barrel. Slide laser back into the adapter ring. Tighten adapter ring screw snugly. If loose, BUG-BEAM will wobble.




## CALIBRATION


- 1 Create a target by marking a sheet of foil with fly sized X's. Permanent marker works best. Tape to wall or box.



- 2 Place yourself so gun barrel is 27" from foil target. This is the ideal distance for effectiveness of salt spray pattern.



- 3 Aim laser, shoot target, and adjust BUG-BEAM accordingly with allen wrench.



SEE INSTALLATION VIDEO AT: [www.bugasalt.com/bugbeam](http://www.bugasalt.com/bugbeam)