
#### Step 1: Downloading and installing the firmware update

# Rocksteady®


#### Download both folders to your Windows PC:


https://drive.google.com/drive/folders/1W\_WT9NICxKC24JQmGW2YHfKaG653c4un?usp=sharing



## Rocksteady®


#### Extract the downloaded files to a new folder:






# Rocksteady®

### Install the updater software:



# Rocksteady®

### Install the updater software:



### Complete the software installation:

welcome to the Multimedia Product Tool Setup
Wizard

The installer will guide you through the steps required to install Multimedia Product Tool on your computer.


WARNING: This computer program is protected by copyright law and international treaties.
Unauthorized duplication or distribution of this program, or any portion of 8, may result in severe civil or criminal penalties, and will be prosecuted to the maximum extent possible under the law.

Cancel 


Rest. Next.>

Click "Next" to begin

**Optional:** Select where you want to install the application




Optional: Uncheck to opt-out



Click "Next" to install


Click "Next" to complete, Then "Close" to complete




#### Step 2: Preparing the installer to update your speakers and subwoofer







April 2024 Rocksteady Stadium
Firmware Updates
Build B3B and Stadium Subwoofer Only



Select "replace"

#### Do not modify, keep the presets



Step 1: Downloading and installing the firmware update


### Type-C DATA cable required



Partially depress and tap the POWER button 15 times is quick succession.

(Follow the same process for the subwoofer and other B3B speakers)





Installation takes approx. 20 seconds.

The speaker will turn off when the installation is complete.

install the firmware

illuminate green when the

connection is made.

#### Troubleshooting and FAQ's



#### 1. The speaker is not connecting to the software (the install down arrow does not turn green indicating a connection):

- If the speaker is not connecting to the software, repeat the process of taping the power button 10-15 times (in other words... try again). If it still won't connect, then it is likely that your Type-C cable is <u>not</u> a DATA cable.

### 2. You can't pair your source device to the speakers after the firmware update.

- The Bluetooth ID name of the speaker will change after the firmware update. You will need to pair to this speaker and connect to the new device name (Rocksteady\_XXXX).

#### What's new?

- Newly developed cone drivers.
- 2. A new wireless system, including new antenna and drivers, for longer range and connectivity.
- 3. New processor, circuitry, and architecture
  - a) Runs cooler and lasts longer, now with 30 hours battery life per charge.
- 4. Dual EQ options
  - a) FULL MODE: Each speaker has a pleasing fullness that fills a room with smooth yet clear full sound.
  - b) CLEAR MODE, the speakers are tuned to approximate studio sound clarity.
  - c) The Rocksteady Stadium subwoofer also features 2 EQ options, optimized for each speaker sound profile; or mix and match.
- 5. Overall and general fixes and updates.