



4. ADDED AS SECONDARY OPERATION.  
 2. ALL CAPACITORS IN MICROFARADS, EXCEPT AS NOTED. Changes from Assembly Rev (A).  
 1. ALL RESISTORS IN OHMS
- NOTES: UNLESS OTHERWISE SPECIFIED.

12340 World Trade Drive  
 San Diego, CA 92128  
 (858) 487-1600  
 FAX 487-6629

**CARVIN**

**Bx600, Bx1200  
 System Master**

DRAWN BY: GEORGE DREYER DATE: 30MAY05  
 APPROVED: DATE:  
 PCB NO: 30-42500 REV: B  
 ASSY. NO: 80-42800 REV: A  
 NO: 80-42122 REV: A  
 REVISED BY: DATE:

B400 Assembly jumpers  
 B401, B402, B403, B404  
 B405, B406, B407, B408  
 B409

B800B1200 Assembly jumpers  
 B801

- CHANGES FOR R1200 ASSEMBLY: 80-42122
1. Add Q110, Q210 (Type: MJL 21194).
  2. Add Q114, Q214 (Type: MJL 21193).
  3. Add R168-R175, R268-R275 (0.22%).
  4. Change C501, C502 to 10Kmf @ 80V.

