


# Assembly Instructions



---

**Console Table**

Model No.  
**HOGA-RY0058**  
**HOGA-RY0108**

---

# Contact Us




## We're here to help you.



Your satisfaction is our top priority. If you encounter any issues with this product, such as missing or damaged parts, we're here to help. Please retain the original packaging and take photos of the packaging and the product, then contact us as soon as possible.


### Warm Tips

1. Carefully read these instructions and keep them for future reference.
2. Check the parts list and confirm everything's there before starting assembly.
3. When assembling, put all parts on a soft, smooth surface like a carpet to avoid scratches.
4. Don't fully tighten screws until all parts are confirmed in place to avoid misalignment.




We recommend using hand tools for assembly.


If an electric screwdriver is used, reduce power and torque to avoid damage to the product.



## Install the Anti-Tip Straps

Using the anti-tip straps can reduce the risk of tipping over, but can not eliminate it.







**⚠ Caution**

Make sure all parts are included. Most board parts are labeled or stamped on the raw edge. Contact us for a free replacement if you encounter any damaged or missing parts.


# Parts List




1 1pc




2 2 pcs




3 2 pcs




4 2 pcs




5 2 pcs



6 2 pcs



7 2 pcs





8 2 pcs


# Hardware List

A	X56+1	B	X40+1	C	X16+1	D	X34+1	E	X4+1	F	X1	G	X4
Ø6X35 mm	Ø15X12 mm	Ø15X10 mm	Ø8X30 mm	Ø7X47 mm	M4X55 mm	M6XØ32 mm							


H	X2+1	I	X2+1	J	X2	K	X2	L	X4	M	X4
3.5X14 mm	4X35 mm	Ø8X40 mm	L250 mm	Ø20 mm	26X13 mm						


1




A	X56
	
Ø6X35 mm	



2




B	X4
	
Ø15X12 mm	




3




B	X12	D	X8
			
Ø15X12 mm		Ø8X30 mm	



4




D	X2	E	X4	F	X1
					
Ø8X30 mm		Ø7X47 mm		M4X55 mm	



5



C	X6	D	X4
			
Ø15X10 mm		Ø8X30 mm	


6






B	X6	D	X2
			
Ø15X12 mm		Ø8X30 mm	





7




B	X6	C	X6	D	X6
					
Ø15X12 mm		Ø15X10 mm		Ø8X30 mm	




8




G	X4
	
M6XØ32 mm	




9







B	X12	C	X4	D	X12
					
Ø15X12 mm		Ø15X10 mm		Ø8X30 mm	

10






H	X2	L	X4	M	X2
					
3.5X14 mm		Ø20 mm		26X13 mm	



I	X2	J	X2	M	X2
					
4X35 mm		Ø8X40 mm		26X13 mm	

12



K	X2
	
L250 mm	

**Thank you for your support!**

