



# StripaCast

## Application instructions



Made in the U.S.A. 

**This product is intended to be installed by a skilled contractor. Deco Products are waterbased and non harmful to the environment but as with all sealers and chemicals proper safety and health precautions should be followed when using. Consult and understand Data, SDS and applicators guide prior to use.**

**Always perform a jobsite test to ensure desired results of the product.**

### DESCRIPTION:

Super StripaCast is a environmentally friendly stripper designed to remove old coatings from concrete paver surfaces. Super StripaCast like all other strippers will react differently to different materials and coatings. For this reason, always do a small test area to ensure desired results. A scrape test is also a good way to determine if the Super StripaCast is degrading the old product.

Most surfaces you will be able to see a failing sealer by the way it breaks down and turns white. However, if you're not sure you can do a water test. In a few different locations (shaded areas, coping around pool, covered areas etc.) pour a small amount of water on the surface. If the water sits on the top of the surface there is a sealer present and stripping should be performed. If the water immediately soaks in it has not been previously sealed and stripping is not required.



**Non Sealed Surface**



**Sealed Surfaces**

### PREPARATION:

#### **COVER AND TAPE OFF ALL AREAS NOT TO BE STRIPPED.**

Cover and tape off all areas not to be sprayed. The use of a paint shield is also a great tool for protecting areas not being stripped. Pre wet all surfaces such as grass, screens, pool cages and other areas within a 10' area being treated. This will help deactivate the StripaCast if over spray during application occurs. Do not get full strength StripaCast on grass or other vegetation. This can cause stress and shock on the vegetation. Keep pets and other animals away during application.

**Keep out of reach from children.**

Open the bucket of StripaCast and mix with a drill and paddle mixer. Move mixer from side to side and up and down for at least one minute mixing completely. Because StripaCast contains a high amount of solids this is a very important step to ensure there is no separation with the material. Pour StripaCast without dilution in to desired sprayer using a strainer or cloth filter. This will help prevent the sprayer tip from clogging during application. Tape and cover all areas not to be sealed. A metal paint guard is also a great alternative for this step. Do not apply in temperatures below 50 degrees or above 95 degrees Fahrenheit. Second coat may be necessary in hotter temperatures. Use caution on windy days. Do not apply to wet surfaces. Best time of day to apply StripaCast is in the morning before the surface can absorb heat from the sun.

**Do not use when rain is expected.**

## APPLICATION:

### Ready to apply

Start at the lowest point and apply in workable sections. With desired sprayer apply a generous amount of StripaCast to surface. After 10 minutes re apply to areas that have dried out or appear to need more help. Dwell time will vary between 20- 40 minutes. Surface will turn milky white when ready to strip. You can also do a scrape test to ensure surface is ready. Take your finger nail or a stiff credit card like object and scrape along the surface. You should see the old sealer scrape away. Apply more StripaCast if this does not happen. Once current section is ready to be stripped apply stripper to the next section to continue at a reasonable pace.

With a turbo tip begin stripping at the lowest point with the water overspray directed away from the rest of the area being stripped. Do this in a slow, small circular motion over the entire job.

## COVERAGE RATES:

**Coverage rates vary depending on many factors.**

Average coverage rate is 1000-1300 square feet per 5 gallon pail.



Training and customer support are available. Contact us directly or your local rep for more info. Videos and other helpful tips are available on our website, Facebook and You Tube channel. If you have a question or are not sure about any part of the application of our products stop installation and contact your local rep for more information.



## LIMITATIONS:

Weather:

Do not let product freeze. Store indoors at temperatures above 32 degrees Fahrenheit. Do not let product sit in direct sunlight or exposed to temperatures above 100 degrees Fahrenheit. Do not apply product when temperatures are below 50 degrees Fahrenheit and over 95 degrees Fahrenheit. Do not apply when rain is imminent.

It is recommended to have a skilled applicator apply our products. Always do a small test area to ensure desired results. Technical support is available by calling 800-500-DECO.

**Pictured are some common sprayers used to apply StripaCast**



**Other equipment recommended to have on hand**

