

Model: INFINITO RIVOLI 33,3X59,2(A) Codes: 100242883 Water absorption: BIII - Revestimiento (10%<=E<=20%)

And shares and the second second second second	
The state of the second second second	
	1
and a grant in the	8
the second	
and provide the second	
	1



DIMENSIONAL FEATURES UNE-EN ISO 10545-2		
Thickness	8.6 MM	+/-5%*
Width	332.5 MM	
Length	590 MM	
Length and width deviation	Below 0.15%	+/-0.3%*
Side straightness deviation	Below 0.15%	+/-0.3%*
Squareness deviation	Below 0.15%	+/-0.3%*
Surface flatness deviation	Below 0.15%	+/-0.4%*
*ISO-13006:2018 UNE-EN 14411:2016		

	MECHANICAL FEATURES UNE-EN ISO 10545-4-6-7-11	
Breaking strength	1343 N	>600N*
Modulus of rupture	32 N/MM2	>=12N/mm2*
Crazing resistance	Resists 3 cycles	
*ISO-13006:2018 UNE-EN 14411:2016		

HYGIENIC FEATURES
UNF-FN ISO 10545-13-14:1995

Chomical	resistance
Cheffical	resistance

Stain resistance

Class "A" for swimming pools and cleaning products B Min.* (resists attack). Minimum Class "B" for acids and bases 3 Min.* Class 5. Easy cleaning with water

*ISO-13006:2018 UNE-EN 14411:2016

SCOPE OF USE

Technical code-1	Use on walls	
	ANTI-SLIP VALUE	
	EN 16165: 2022 / ASTM C1028	
Friction (dry)	No Aplica	
Friction (wet)	No Aplica	
Slip resistance (dcof)	No Aplica	
*ISO-13006:2018 UNE-EN 14411:2016		



Do not use cleaning agents containing hydrofluoric acid. It is recommended to fix tiles with a minimum joint of 1,5 mm. Do not fix without joint. For big sizes, it is recomended to fix with mortars containing polymeric additives and to use the double glueing technique. Mosaic tiles must be grouted. This document is only commercial and cannot be used as expert opinion, documentary evidence or in any legal or administrative procedure unless authorized by PORCELANOSA S.A.

100242883 INFINITO RIVOLI

PORCELANOSA Grupo

	PACKING	
Sales units per box	1.182825 M2/BOX	
Sales units per pallet	56.775618 M2/PAL	
Sales units per unit	0.197138 M2/PIECE	



Do not use cleaning agents containing hydrofluoric acid. It is recommended to fix tiles with a minimum joint of 1,5 mm. Do not fix without joint. For big sizes, it is recomended to fix with mortars containing polymeric additives and to use the double glueing technique. Mosaic tiles must be grouted. This document is only commercial and cannot be used as expert opinion, documentary evidence or in any legal or administrative procedure unless authorized by PORCELANOSA S.A.