

Model: LUCERNA SILVER L 120X120(A) Codes: 100314132 Water absorption: Bla - Porcelanico (E<=0.1%)





DIMENSIONAL FEATURES UNE-EN ISO 10545-2			
Thickness	8.5 MM	+/-5%*	
Width	1200 MM		
Length	1200 MM		
Length and width deviation	Below 0.15%	+/-0.3%*	
Side straightness deviation	Below 0.15%	+/-0.3%*	
Squareness deviation	Below 0.15%	+/-0.3%*	
Surface flatness deviation	Below 0.15%	+/-0.4%*	
*ISO-13006:2018 UNE-EN 14411:2016			

MECHANICAL FEATURES UNE-EN ISO 10545-4-6-7-11			
Breaking strength	2366 N	>1300N*	
Modulus of rupture	53 N/MM2	>=35N/mm2*	
Abrasion resistance	PEI 4 / 1500v		
Crazing resistance	Resists 3 cycles		
*ISO-13006:2018 UNE-EN 14411:2016			

HYGIENIC FEATURES UNE-EN ISO 10545-13-14:1995			
Chemical resistance	Class "A" for swimming pools and cleaning products (resists attack). Minimum Class "B" for acids and bases	B Min.*	
Stain resistance	Class 5. Easy cleaning with water	3 Min.*	
*ISO-13006:2018 UNE-EN 14411:2016			

	SCOPE OF USE			
Technical code-1	Use on heavy traffic floors			
ANTI-SLIP VALUE EN 16165: 2022 / ASTM C1028				
Slip resistance (pendulum-wet)	CL2			
Slip resistance (ramp)	R-10	TONO 5 / ID 1236*		
Slip resistance (bare feet)	В	16912 (4C2)*		
***** ********************************				

*ISO-13006:2018 UNE-EN 14411:2016



Do not use cleaning agents containing hydrofluoric acid. It is recommended to fix tiles with a minimum joint of 1,5 mm. Do not fix without joint. For big sizes, it is recomended to fix with mortars containing polymeric additives and to use the double glueing technique. Mosaic tiles must be grouted. This document is only commercial and cannot be used as expert opinion, documentary evidence or in any legal or administrative procedure unless authorized by PORCELANOSA S.A.

100314132 LUCERNA SILVER L

PORCELANOSA Grupo

	PACKING	
Sales units per box	1.440092 M2/BOX	
Sales units per pallet	60.483871 M2/PAL	
Sales units per unit	1.440092 M2/PIECE	



Do not use cleaning agents containing hydrofluoric acid. It is recommended to fix tiles with a minimum joint of 1,5 mm. Do not fix without joint. For big sizes, it is recomended to fix with mortars containing polymeric additives and to use the double glueing technique. Mosaic tiles must be grouted. This document is only commercial and cannot be used as expert opinion, documentary evidence or in any legal or administrative procedure unless authorized by PORCELANOSA S.A.