


THE BOSS KIT QUICK INSTALL GUIDE



STEP 1: MOUNT ZONE LIGHTS

BOTH ZONE LIGHTS SHOULD BE MOUNTED USING THE SUPPLIED LIGHT CLAMPS, ON EACH SIDE OF THE OVERHEAD GUARD, FACING DOWN TOWARDS THE GROUND.



STEP 2: MOUNT ARC LIGHT

ARC LIGHT CAN BE MOUNTED TO THE BRACKET ON THE REAR CENTER OF THE OVERHEAD GUARD. THE LIGHT SHOULD FACE DOWN TOWARDS THE GROUND.



STEP 3: POWER

THE BOSS KITS ARE MULTI VOLTAGE. FROM 12V TO 80V.

RED WIRES = POWER
BLACK WIRES = GROUND

ARC LIGHTS COME STANDARD WITH DEUTSCH CONNECTOR.

IF NOT CONNECTING TO ANOTHER DEUTSCH CONNECTOR, SIMPLY CUT THE WIRE BEFORE THE CONNECTOR.



STEP 4: LIGHTS ADJUSTMENT

ADJUST LIGHTS TO DESIRED COVERAGE AREA.



ARC LIGHT ANGLE



2 ZONE LIGHTS' ANGLE

