


Install Guide for TYCO TOUCH OPTIR Touch Screen with Glass and Custom Mount

1. Carefully remove side Velcro (hook) strips. Leave the Velcro (loop) strips on the touch screen.



2. The Velcro (hook) can be added to the left and right side of the monitor's front bezel. For thin bezel monitors, it is normal if the Velcro wraps around the sides and to the back.



3. Carefully align frame to your monitor so that the viewable area matches as closely as possible to the open touch area of the touch screen.



4. Once aligned, press the touch screen firmly into place and plug in USB cable to PC's empty USB port.

