


# RESISTANCE COLOR CODE CHART

larē



1st Digit	2nd Digit	3rd Digit	Multiplier	Tolerance
0	0	0	1	
1	1	1	10	1%
2	2	2	100	2%
3	3	3	1000	
4	4	4	10000	
5	5	5	100000	
6	6	6	1000000	
7	7	7		
8	8	8	0.1 Gold	5% Gold
9	9	9	0.01 Silver	10% Silver

