


Wiring Diagram

**MCS-5
4-Switch Panel
Rixens Enterprises Inc.
© 2018**

1. Ground
2. Power 12VDC fused 10A
3. Furnace Start •to Relay Harness
4. Hot Water Aquastat out (bridge 4-5 when Aquastat not used)
5. Hot Water Aquastat in
6. Water Pump +
7. Fans +
8. n/a
9. T-Stat in •to Relay Harness
10. T-Stat out •to Relay Harness



Note: Wire shown in cyan are not supplied, use at least 16 AWG

Note: No polarity

← Harness Label connect leads color to color