



# POR 15<sup>®</sup>

## Six Pack

### POR-15<sup>®</sup> Rust Preventive Permanent Coating

- Great for Small Projects
- Protects Old & New Components
- No Need to Remove ALL Rust Before Applying
- Professional Use

## STOP RUST PERMANENTLY!

POR-15<sup>®</sup> Rust Preventive Coating is a high performance coating designed for application directly on rusted, seasoned and new metal surfaces. As a non-porous coating, it seals and protects many surfaces from water, chemicals, salt, and other corrosive contaminants. POR-15<sup>®</sup> Rust Preventive Coating is an effective anti-corrosive and rust preventive coating that offers superior chemical resistance due to its dense, cross-linked molecular composition and non-porous attributes.

### Features:

- Each can covers 6 sq. ft. with 2 coats applied
- Convenient packaging, easy to carry
- Single component permanent moisture cured urethane
- Non-porous coating, chemical resistant
- Self-leveling when applied with a brush
- Uses: automotive, marine and industrial
- Protects your investment
- Completely waterproof
- Abrasion chemical, stain and impact resistant
- Does not crack, chip, or peel from the surface substrate
- Eliminates the need for a sacrificial zinc primer system
- Effectively adapts to expansion and shrinkage of surface caused by temperature changes
- Heat resistant up to 450°F / 232°C.



PRODUCT	Color	SIZE	CODE
Six Pack	Gloss Black	4 oz.	45006



WE KNOW WHAT **PERMANENT** MEANS!<sup>®</sup>

**POR**  
PRODUCTS  
PORproducts.com



# Product Information

## Six Pack Rust Preventive

Permanent Coating #45006



### Product Description

COLOR: Gloss Black

Coverage: 6 sq. ft. per 4 oz. can, with 2 coats applied., depending on surface.

POR-15® Rust Preventive Coating is designed for application directly on rusted, sandblasted, and seasoned metal surfaces. It dries to a rock-hard, non-porous finish that won't chip, crack, or peel, and it prevents rust from recurring by protecting metal from further exposure to moisture. POR-15® Rust Preventive Coating is sensitive to UV light and must be topcoated when prolonged exposure to sunlight is possible. Topcoating is not required for areas not exposed to sunlight.

### Application Information

**Surface Preparation:** To coat rusted or bare metal surfaces. Remove grease, oil, and other foreign substances using POR-15® water-based cleaner and prep products per the listed instructions.

Stir POR-15® Rust Preventive Coating thoroughly, then dispense a quantity of POR-15® Rust Preventive Coating into a separate container to avoid contamination.

**APPLICATION:** Apply in thin coats. Always apply a minimum of two coats. If necessary, only thin with POR-15® Solvent, up to 5%. POR-15® Rust Preventive Coating may be recoated or topcoated when dry to the touch with a slight "finger drag", typically 2 to 6 hours. To coat over cured POR-15® Rust Preventive Coating, scuff the surface with 320 grit sandpaper until gloss is dull, and then apply coating.

**CLEAN UP:** Use POR-15® Solvent for clean-up, which must be done before POR-15® Rust Preventive Coating dries; once dry POR-15® Rust Preventive Coating cannot be removed by solvent.

For skin protection wear protective clothing and gloves; for eye protection wear safety glasses with side shields or splash-proof goggles. Avoid skin contact. Remove from skin at once to avoid temporary staining. Moisture will shorten the life of unused POR-15® Rust Preventive Coating; seal can immediately after dispensing. Transport and Store Upright Only and never in an area of sun or heat exposure.

POR-15® Rust Preventive Coating, like all POR-15® coatings, should always be stirred, not shaken.

### Safety Information

**WARNING!** Vapor harmful. May affect the brain or nervous system causing dizziness, headache or nausea. Causes eye, nose, throat and skin irritation. Overexposure may cause kidney damage.

**NOTICE:** Reports have associated repeated and prolonged occupational overexposure to solvents with permanent brain and nervous system damage. Intentional misuse by deliberately concentrating and inhaling the contents may be harmful or fatal.

**INDIVIDUALS WITH LUNG OR BREATHING PROBLEMS OR PRIOR REACTION TO ISOCYANATES MUST NOT BE EXPOSED TO VAPOR OR SPRAY MIST.** Do not breathe vapor or spray mist. Ensure fresh air entry during application and drying. If you experience eye watering, headache or dizziness or if air monitoring demonstrates vapor/mist levels are above applicable limits, wear an appropriate, properly fitted respirator (NIOSH approved) during and after application. An airline respirator (NIOSH approved) is recommended. A vapor/ particulate matter respirator (NIOSH approved) may be appropriate where airborne monitoring demonstrates vapor levels below ten times the applicable exposure limits. Follow respirator manufacturer's directions for respirator use.

Use Only With Adequate Ventilation.

Keep away from heat and flame. Prevent build-up of vapors by opening all windows and doors to achieve cross-ventilation. Avoid contact with eyes, skin and clothing. Wash thoroughly after handling.

**FIRST AID:** FOR INHALATION: If you experience difficulty breathing, leave area to obtain fresh air. If continued breathing difficulty is experienced, get medical attention immediately. IF SWALLOWED: DO NOT induce vomiting; immediately call Poison Control Center and have label available. FOR SKIN CONTACT: Wash thoroughly with soap and water. Remove contaminated clothing and shoes. Wash clothing before reuse. Get medical attention if skin irritation occurs or you feel unwell. FOR EYE CONTACT: Flush eyes immediately with plenty of fresh water. Remove contact lenses if possible. Continue eye flushing with water for at least 15 minutes and get medical attention immediately.

KEEP OUT OF REACH OF CHILDREN.

If spilled, contain spilled material and remove with inert absorbent. Dispose of contaminated absorbent, container and unused contents in accordance with local, state and federal regulations. Before opening container, read all warning labels. Follow all precautions.

**WARNING!** If you scrape, sand, or remove old paint, you may release lead dust. LEAD DUST IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH-approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to [www.epa.gov/lead](http://www.epa.gov/lead).

**⚠️WARNING:** This product can expose you to chemicals including Carbon Black, and Cumene, which are known to the State of California to cause cancer. For more information, go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov).

Refer to Material Safety Data Sheet available from your dealer for further safety and handling information.

**P.O.R. PRODUCTS** 800-457-6715  
**PORproducts.com**

P.O.R. Products, 38 Portman Rd, New Rochelle, NY 10801

© 2018 P.O.R. Products © POR-15 is a registered trademark of P.O.R. Products.