



QuickDraw Deployment Straps (20RES-42)

Quick Draw Deployment Straps




1. Pass the webbing with snap buckle behind the front belt loop of the PFD, making sure that the quick release opens towards the zipper.



2. Pass the other half of the webbing and snap buckle behind the other side of the belt loop and secure the buckle.



3. Repeat on the other side.




4. Pass the strap through the slider on the center back of the PFD.



5. Pass the strap through the slider on the end of the strap.



6. Pull the strap so that it anchors tight against the PFD.



7. Pass the strap through the belt loops along the bottom perimeter of the PFD from back to front.



8. Secure the end of the Strap in the quick release buckle and repeat on the other side.

