**HAMMER ROO CERAMIC COATINGS ARE SCIENTIFICALLY FORMULATED TO PENETRATE MICROSCOPIC SURFACE PORES TO** PROVIDE A BONDING LAYER OF PROTECTION THAT IS INCREDIBLY STRONG AND RESILIENT.

**CERAMIC COATINGS ARE IDEAL IN** PREVENTING AND MINIMIZING **SURFACE DAMAGE INCLUDING:** ABRASION, CHEMICAL STAINS. UV DAMAGE AND OXIDATION.

# CERAMIC CERAMIC COATING COATING



**HAMMERROO.COM.AU** 

## **APPLICATION INSTRUCTIONS**













## **PREPARATION**

MAKE SURE THE SURFACE IS CLEAN & DRY. ALLOW PREVIOUS COATINGS TO COMPLETELY CURE BEFORE APPLICATION OF CERAMIC COATING.

### **APPLICATION**

WRAP THE MICROFIBER CLOTH OVER APPLICATOR SPONGE.

APPLY A SMALL AMOUNT OF CERAMIC COATING TO THE MICROFIBER CLOTH AND APPLY USING A CROSS HATCH PATTERN.

**WORK IN 40CM X 40CM SECTIONS.** 

### TIP:

OUTLINE THE PERIMETER &
THEN FILL THE INSIDES OF
THE PERIMETER.
FIRST GO WITH THE GRAIN, THEN
GO AGAINST IT. ALTERNATE FOR
EVERY PASS.



#### **APPLICATION**

ONCE THE CERAMIC COATING STARTS TO DRY IT WILL GIVE MORE RESISTANCE (WITHIN 1 - 3 MINS DEPENDING ON TEMPERATURE).

AT THIS POINT FINISH THE PASS THEN USE A CLEAN MICROFIBER CLOTH TO EVEN OUT FINISH USING SAME ALTERNATING CROSS HATCH PATTERN.

#### TIP:

USE LIGHT PRESSURE ONLY -THE WEIGHT OF YOUR HAND IS ENOUGH. EXCESSIVE PRESSURE WILL REMOVE CERAMIC COATING.

ONCE FINISHED THE WHOLE SURFACE EVEN OUT USING CLEAN MICROFIBER CLOTH AS ABOVE.

REPEAT PROCESS FOR ADDITIONAL COATS. WE RECOMMEND 2-3 COATS OR UNTIL DESIRED FINISH IS ACHIEVED. COVERAGE APPROX. 5ML/M2 PER COAT
RECOATABLE AFTER 1 HOUR
TOUCH DRY AFTER 24 HOURS
DO NOT EXPOSE TO
WATER WITHIN 24 HOURS.
WAIT 3 DAYS BEFORE EXPOSING TO
WATER FOR OPTIMAL RESULTS

#### **MAINTENANCE**

CLEAN WITH SLIGHTLY DAMP CLOTH OR PH NEUTRAL SOLUTION. IF SCRATCHES APPEAR OVER TIME, REAPPLY AS NEEDED.



## **SAFETY**

ALWAYS USE PROPER SKIN
PROTECTION.

APPLY IN A WELL VENTILATED
AREA AWAY FROM DIRECT
SUNLIGHT SUCH AS
GARAGE OR SHADED AREA.
DO NOT INGEST.

FOR MORE INFORMATION CONTACT US AT HAMMERROO.COM.AU