





A (x2)




C (x1)



D (x1)



E (x1)



F (x1)



G (x1)



H (x1)



B (x2)



I (x1)



J (x8)
M5x12



K (x1)
M5x16



L (x1)
M10x20



M (x3)
M6x10



N (x8)
M5



O (x1)
4mm



P (x1)
6mm



Q (x1)



M-A (x4)
M6x14



M-B (x4)
M8x20



M-C (x4)
D8



M-D (x8)



M-E (x4)
M4x12




M-F (x4)
M5x12




M-G (x4)
D5


1




2 Clamp Mounting




2 Grommet Mounting




2 Grommet Mounting




2 Grommet Mounting




2 Grommet Mounting




3




3




3



3




3




4a

VESA 200x200




4b


VESA 200x100




5a




5b



5c




3




4a

VESA 200x200




4b


VESA 200x100



5a



5b



5c

