


1



Electric drill



Drill bit



Tape measure



Pencil




Screwdriver



3A




3B




1C


2



3




3A



3B

1C

4



5

