

## **Supreme**-HYDROPONICS

By Danner Manufacturing, Inc.



IMPORTANT: The DRAIN FITTING must <u>always</u> be larger than the FILL FITTING to allow sufficient draining of flood table to prevent overflow.



DANNER Mfg. INC. • Islandia, New York 11749 631-234-5261 www.dannermfg.com