

Walk-Through Ornament Graphic Installations Instructions



1. Identify the three sections of your graphic (left panel, center panel, and right panel). Pinpoint the side of the center panel that has only four screws on it — this is the front of your graphic.



2. Remove the four screws from the center panel to remove the graphic (to be reattached later).




3. Prepare to connect all three panels, aligning the holes on both the left and right panels with the holes on the center panel.



4. Insert the provided bolts and tighten.



5. Once all bolts are secure, reattach the center panel graphic using the provided self-tapping screws.



6. Attach entire graphic to the back panel of your Walk-Through Ornament using the provided hose clamps.



6a. (Graphic shown after being attached to the Walk-Through Ornament frame.)



7. Enjoy your finished product!