

Set Up Instructions WLM-2000E

Step 1: Assemble straight poles by pressing and pushing together.




Step 5: Zip the edge of graphic beyond the center point as shown to hold the center pole in place. Zip the remaining side and bottom to meet at the corner.







Step 2: Connect all corner sections to curved and straight sections of the frame by matching shape symbols on pipes.



Step 3: Insert feet into base to complete assembled frame shown.



Step 4: Unzip print and lay image face up. Slide print onto frame like a pillow case.



Step 6: Complete.




LIGHTS: (OPTIONAL) Position as desired and tighten knob to hold in place.

WARNING! Over tightening may cause damage to fabric image.


Set Up Instructions WLM-2000F

Step 1: Assemble straight poles by pressing and pushing together.







Step 4: Insert feet into base to complete assembled frame shown.




Step 5: Unzip print and lay image face up. Slide print onto frame like a pillow case.




Step 6: Zip the edge of graphic beyond the center point as shown to hold the center pole in place. Zip the remaining side and bottom to meet at the corner.











LIGHTS: (OPTIONAL) Position as desired and tighten knob to hold in place.


WARNING! Over tightening may cause damage to fabric image.



Set Up Instructions


WLM-2000A

Step 1: Assemble straight poles by pressing and pushing together.




Step 3: Insert feet into base to complete assembled frame shown.


Step 4: Unzip print and lay image face up. Slide print onto frame like a pillow case.



Step 5: Zip the edge of graphic beyond the center point as shown to hold the center pole in place. Zip the remaining side and bottom to meet at the corner.



Step 6: Complete.





LIGHTS:

(OPTIONAL) Position as desired and tighten knob to hold in place.


WARNING! Over tightening may cause damage to fabric image.



Set Up Instructions

WLM-2011B


Step 1: Assemble the two long curved and straight sections together. The frame is symmetrical and either of the curved sections can be top or bottom.




Step 5: Zip the edge of graphic beyond the center point as shown to hold the center pole in place. Zip the remaining side and bottom to meet at the corner.




Step 2: Connect all corner sections to curved and straight sections of the frame by matching shape symbols on pipes.



Step 3: Complete assembled frame shown.



Step 6: Complete.







LIGHTS:


(OPTIONAL) Position as desired and tighten knob to hold in place.

WARNING! Over tightening may cause damage to fabric image.

Set Up Instructions

WLM-PANEL CONNECTION

FEET





CLAMPS

