

The FMEA process is carried out in seven steps.

These seven steps provide a systematic approach to perform a Failure Mode and Effects Analysis and serve as a record of the technical risk analysis.




Figure 1.6-1 FMEA 7 Step Approach