

### **INSTALLATION INSTRUCTIONS - INS255**

# OIL SEPARATOR KIT

Part # 1895 // 2005 - 2010 Ford Mustang 4.0 liter V6



### No Special Tools required



Install Time: Approximately 1 hour.



Difficulty: Easy



IMPORTANT: All appropriate safety equipment and gear must be used during the installation of this or any BBK Performance products or any time you work on a vehicle.

BBK Performance accepts no responsibility for injuries or damage caused by or during the installation of this product.





### STEP 1



# From this side of the oil separator the hose will go to intake.

## STEP 2



After assembling Oil Separator Kit as shown in pic install it on the vehicle with supplied hardware and clamping down hoses at valve cover/intake manifold connections and strut tower mount.

#### STEP 3





IMPORTANT: All appropriate safety equipment and gear must be used during the installation of this or any BBK Performance products or any time you work on a vehicle. BBK Performance accepts no responsibility for injuries or damage caused by or during the installation of this product.

UPDATED LAST: March 2019





BBK PERFORMANCE LLC / For any questions, email us: 3060 Performance Circle / TECH@BBKPERFORMANCE.COM Deland, FL 32724 /



### FOLLOW THESE INSTRUCTIONS CAREFULLY TO ENSURE CORRECT FITMENT AND OPERATION

## WE RECOMMEND DRAINING OF A IR OIL SEPARATOR EVERY A,000 MILES OR AS NEEDED; THIS WILL OF COURSE DEPEND ON DRIVING CONDITIONS! A

For normal day to day driving check every 1,000 miles until a baseline is established. A good baseline is to drain the AirA

Oil Separator Awhen it is about HALF full. This will Aary Awith temperatures (cold winters vs. hot summers). Simply Unscrew the base of A
the oil separator – drain the oil and clean out the canister base. Once clean re-install and you are good to go for another 1000+ miles. A



IMPORTANT: All appropriate safety equipment and gear must be used during the installation of this or any BBK Performance products or any time you work on a vehicle.

BBK Performance accepts no responsibility for injuries or damage caused by or during the installation of this product.

UPDATED LAST: March 2019

