



FRAG1921

RECIPE - WAX MELT

PANDORA'S BOX IN HPM

CANDLE SHACK

DESCRIPTION

PANDORA'S BOX

TOP NOTES - BERGAMOT, ORANGE, GREEN LEAF, NUTMEG, PEPPER

HEART NOTES - CLOVE, LAVENDER, PATCHOULI, AMBER

BASE NOTES - VETIVER, MOSS, SANDALWOOD, CEDARWOOD, TONKA

INGREDIENTS FOR EACH CANDLE

[81g High Performance Melt Blend](#)

[9g Pandora's box Fragrance Oil](#)

[0.162g Bekro Dye - 78/3297 - Turquoise](#)

[1x Metal Pouring Jug](#)

[0.405g Lagoon - Mica Powder](#)

[1x Clamshell - Hearts](#)

USAGE RECOMMENDATIONS

Option 1 - Homogeneous look (beginner level)

- Measure the wax and heat it in a suitable container or double boiler at 60°C. This wax is not suitable for microwave use.
- Once melted, add the dye, fragrance and mica powder, mixing until homogeneous in between each step.
- Pour your mixture into the clamshell.
- Leave your wax melt to set for 48 hours before using it.

Option 2 - Artisanal look (beginner level)

- Measure the wax and heat it in a suitable container or double boiler at 60°C. This wax is not suitable for microwave use.
- Once melted, add the dye and fragrance, mixing until homogeneous in between each step.
- Add the raw mica roughly into the shapes in the clamshell.
- Slowly pour your mixture into the clamshell.
- The mica will spread messily across the bottom (which will become the top) and give your wax melts an almost gold-sparkling look.
- Leave your wax melt to set for 48 hours before using it.

Option 3 - Elegant look (advanced level)

- Measure the wax and heat it in a suitable container or double boiler at 60°C. This wax is not suitable for microwave use.
- Once melted, add the dye and fragrance, mixing until homogeneous in between each step.
- Take 3g of the wax mixture and place it in another warm container.
- Mix the mica with the 3g of the mixture and heat it to bring the temperature back to 60°C.
- This will allow the use of a pipette for the next step without the mixture solidifying in the pipette. Keeping the mixture hot will keep it fluid.
- Use a pipette to take up some of the hot mica mixture and carefully fill each shape at the bottom of the clamshell with the mixture. They do not have to be completely full.
- Try to spread the mixture across all four tree shapes evenly.
- Leave it for 2 minutes, then fill the clamshell with the main mixture.
- The mica will set in each shape, giving a beautiful smooth golden shape on the top of each melt portion, much like a gold leaf.
- Leave your wax melt to set for 48 hours before using it.