
CARVER MULTICLAMP




ASSEMBLY INSTRUCTIONS




If you have a QR reader on your mobile phone, please visit our web site.





NOTES:

 * <u>THE MATING FACES MUST BE KEPT CLEAN AND FREE FROM DAMAGE.</u>
 *<u>THE CLAMP MUST NOT BE ASSEMBLED / USED WITHOUT THE SPLIT PIN IN PLACE. IF THE PIN IS</u> DAMAGED / MISSING THEN REPLACE WITH SPARES PART No C301248 BELOW.
 **<u>DO NOT USE AN EXTENSION BAR ON THE ALLEN KEY TO TIGHTEN THE CAP SCREW OTHERWISE</u> <u>THE INTERNAL THREADS IN THE BAR ARE LIKELY TO STRIP. IN THE EVENT THAT THIS THREAD</u> DOES GET DAMAGED IT CAN BE REPLACED; REMOVE THE DAMAGED HELICOIL AND REPLACE IT WITH A NEW ONE - SEE PART No C301247 BELOW.




NOTES:

* <u>THE MATING FACES MUST BE KEPT CLEAN AND FREE FROM DAMAGE.</u>
 *<u>THE CLAMP MUST NOT BE ASSEMBLED / USED WITHOUT THE SPLIT PIN IN PLACE. IF THE PIN IS DAMAGED / MISSING THEN REPLACE WITH SPARES PART No C301248 BELOW.</u>
 **<u>DO NOT USE AN EXTENSION BAR ON THE ALLEN KEY TO TIGHTEN THE CAP SCREW OTHERWISE THE INTERNAL THREADS IN THE BAR ARE LIKELY TO STRIP. IN THE EVENT THAT THIS THREAD DOES GET DAMAGED IT CAN BE REPLACED; REMOVE THE DAMAGED HELICOIL AND REPLACE IT WITH A NEW ONE - SEE PART No C301247 BELOW.
</u>

SPARE PARTS

PART NUMBER	DESCRIPTION						
C301243	BAR						
C301244	STANDARD REACH HEAD						
C301245	LONG REACH HEAD						
C301000	STANDARD REACH MOVING ARM	St Chap					
C301100	LONG REACH MOVING ARM						
C301246	M10 x 1.5 x 45 SOCKET HEAD SCREW						
C301247	M10 x 1.5 x 1.5D HELICOIL						
C301248	SPLIT SPRING TENSION PIN						
C301249	ALLEN KEY						



CONFIGURATION	S	А	A1	A2	В	B1	B2	B3	B4	L	L1
STANDARD REACH	320	25	21.5	76	32	65	55	32	76	450	45
LONG REACH	320	25	21.5	76	32	120	106	32	76	450	45

Carver and Co (Engineers) Ltd St Mary's Road, Nuneaton, Warwickshire, CV11 5AU. Telephone:+44 (0)2476 377540 Fax: +44 (0)2476 388578 Email: sales@ carver.co.uk Web: www.carver.co.uk