## Phinbased<sup>°</sup>

### Binding, mounting and ski maintenance

#### **BINDING MOUNT GUIDELINES**

Measurements are taken from the tail of the ski, in centimeters. Please check the binding screws' length before mounting!

#### WARNING!

Skinbased skis are designed for backcountry skiing only. Before using this product, read and understand all instructions and familiarize yourself with its proper use, capabilities and limitations. Incautious or improper use can result in severe injury or death! The manufacturer, distributor, wholesaler, and retailer are not liable for any personal injuries sustained by the use or misuse of this product.

#### **OAC SKINBASED MOUNT POSITION**

MODEL	OAC EA FRONT SCREW (cm)	3 PIN FRONT SCREW (cm)	PIN LINE  NNN/Tech/3 Pin (cm)	DRILL BIT
KAR 149	81	83	80,5	4,1/13mm
WAP 129	71	73	70,5	4,1/13mm
POH 100	54,5	-	-	4,1/9mm
XCD GT 160	85	87	84,5	4,1/13mm
XCD GT 137	73	75	72,5	4,1/13mm
XCD BC 160	85	87	84,5	4,1/13mm

# FOR BASE MAINTENANCE we recommend







DO NOT USE hot waxes/iron for maintaining the base or climbing skin. All skis come factory pre-waxed and are ready to go.



www.skinbased.com