

## CYL-CK CASTER KIT

## KIT SHOULD INCLUDE:

(2) - SWIVEL CASTER ASSEMBLIES




(4) - 1/2-13 UNC x 1 1/2 LG HEX HEAD BOLT, WASHER, & LOCK NUT (FOR USE ON SWIVEL ASSEMBLY)





## **INSTRUCTIONS:**

- 1. DRILL HOLES IN THE LOCATIONS SHOWN BELOW IN THE CYLINDER CADDY BASE PAN. (NOTE: HOLES NEEDED ON BOTH SIDES OF THE UNIT)
- 2. MOUNT ŚWIVEL CASTER ASSEMBLY ON ENDS OF UNIT



	UNLESS OTHERWISE SPECIFIED: REMOVE ALL BURRS AND SHARP EDGES			Vestil Manufacturing Co.			
	DIAJENISIONIS ARE IN INICUES			DESCRIPTION:			
	CONCENTRIC	.006 TIR	.060 TIR	INSTRUCTIONS, CYL CASTERS			
	ANGLES	± 0° 30'	± 1° 0'				
		x.xxx ± .005		MODEL NO: CYL-CK			
		x.xx ± .010		DRAWN BY: K.YOUNG	DATE: 9/12/05	SCALE: 1:6	SIZE
PROPRIETARY AND CONFIDENTIAL THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF VESTIL MANUFACTURING CO. ANY REPRODUCTION IN PART OR AS A WHOLE	DECIMALS	x.x ± .025	± .015		7/12/00	00/ KEE. 1.0	5122
	FRACTIONS	± 1/32	± 1/16	MAT'L: AS LISTED			A
	TOLERANCES	MACHINE	WELDMENT				
				DWG. NO.			
WITHOUT THE WRITTEN PERMISSION OF VESTIL MANUFACTURING CO. IS PROHIBITED.	33-001-155 DO NOT SCALE DRAWING			33-126-007			
3	2					1	

5 4 3