

Shadow Vision 12" Instructions

If you prefer to use a connector of your choice, you may cut the DT connector off. This does not affect the warranty. Please make sure you remember the cable positions before making the cut so that you know which cable has which function.

PARTS INCLUDED

- A. 2x Universal side mounting bracket
- B. 2x M8 stainless steel bolts
 - 2x M8 Allen bolts
 - 2x M8 spring washers
 - 2x M8 nuts
- C. Shadow Vision led light




TOOLS REQUIRED

- Allen key
- Wrench 13 mm



Wiring position



Cable Position	Cable Function	Cable Colour
1	Grounding (Negative -)	Black
2	Driving beam (10-30V DC +)	Red
3	Beacon (10-30V DC +)	Yellow