
AK-WS ASSEMBLY INSTRUCTIONS



PART LIST

1-MAST

2-CONNECTING PIPE

8-SELF-TAPPING SEREWS

4-WASHER

4-SPRING WASHER

4-HEXAGON BOLT

1-LEVELER

BOLTS ARE SCREWED IN PLACE