

Z-RACK(KNOCK DOWN) ASSEMBLY INSTRUCTIONS

- | PART LIST | |
|-----------|--|
| 1-BAR | |
| 2-MAST | |
| 1-BASE | |
| 2-LEG | |
| 4-BOLT | |
| 4-NUT | |
| 4-WHEEL | |
- BOLTS ARE SCREWED
IN PLACE

