Contact Us: FACTORY UTV LLC.

9237 Beatty Drive Sacramento, CA 95826



U.H.M.W. Skid Plate / Under Armor Package

Ultra. High. Molecular. Weight. polyethylene all terrain skid plate / under armor kit for UTV's

Installation Guide (Ultimate Package)

Polaris Ranger 150 (2018+)



Polaris Ranger 150 (2018+) Instructions



Front Skid Plate:

Install: (1x) 1/4"-20 x 3/4" Flange Bolt and (1x) Counter sunk washer,

with (1x) 3/8" large Zinc Washer and (1x) ¼"-20 Ny-Lock Nut, fastened behind chassis frame in Front Skid: (C) location. Install: (1x) ¼"-20 x 2¼" Hex Bolt and (1x) Counter sunk washer

with (1x) 1 - 1/2" Nylon Spacer, (1x) $\frac{1}{2}$ " Gold Washer, and (1x) $\frac{1}{2}$ " -20 Ny-Lock Nut in Diff. Skid: (B.S1) location.



Main Skid Plate:

Align edge with front skid plate and along sides of utv, may need the use of *vice clamps or car jack to aid during install. Using main skid plate as a template, mark the center of (A) locations, drill $^{25}/_{64}$ holes in to chassis for nutserts. For the remaining four rear (A.n) locations; mark, drill $\frac{9}{32}$ holes in to chassis for use with bolts and ny-lock nuts.

Install: (6x) ¼"-20 Nutserts in: (A) locations. You will need the use of a nutsert tool to install nutserts:

Ensure all Nutserts are fastened securely and crimped flush before installing skid pate bolts.

Install main skid plate with: $(6x) \frac{1}{4}$ -20 x $\frac{3}{4}$ Flange Bolts and (6x) Counter sunk washers in (A) locations. Install (4x) $\frac{1}{4}$ "-20 x $\frac{3}{4}$ " Flange Bolts, (4x) Gold washers with

(4x) Counter sunk washers and (4x) Ny-lock nuts in rear (A.n.) locations.



Swingarm Guard:

(Remove stock chain quard) May need the use of *vice clamps to hold in place, Check for clearance before drilling in (F) locations. Using stock drain holes as a guide, drill a $^9/_{32}$ " hole through frame.

Install: $(2x) \%''-20 \times 2 \%''$ Counter Sunk Bolts, (1x) %'' Gold Washer, (1x) %''-20 Ny-Lock Nut in: (F) locations. Install: (Ix) $\frac{1}{4}$ -20 x 1 $\frac{1}{4}$ Counter sunk bolt using *DI clamp* and *D2 clamp* -"D" clamps over tubing with

(1x) ¼" Gold Washers and (1x) ¼"-20 Ny-Lock Nut in each Swingarm guard: (C.DI and C.DZ) locations.

Install: (1x) 1/2" -20 x 1 1/2" Counter Sunk Bolt, (1x) 1/2" Nylon spacer, with

(1x) ¼" Gold Washer, and (1x) ¼"-20 Ny-Lock Nut in Swingarm guard: (E.1/2) locations.




Ensure all bolts are fastened securely when complete, do not over tighten.




A-Arm Guards

Install: (1x) 1 x 1"D" clamp over A-Arm tubing w/ (1x) \%"-20 x 1\%" Counter Sunk Bolt, (1x) 1/4" Gold Washer, and (1x) 1/4"-20 Ny-Lock Nut in each A-Arm guard: (D.1) location.



* Ensure Clearance For Turn Radius & Vertical Travel Before Fastening ALL Bolts Securely




Drilling Instructions: *

Use a: 25/64^{th"} drill bit for 1/4 x 20 Nutsert installation

Use of a Nutsert tool is required. Keep tool level with surface until bottom of nutsert crimps securely.

Use a: 9/32 ^{nd"} drill bit for <u>1/4 x 20 Nut and bolt</u> installation

Finger Thread All Bolts Prior To Fastening Securely With Power Tools. Do not over tighten



Polaris Ranger 150 (2018+) Skid Plate Hardware kit

