Contact Us: FACTORY UTV LLC.

9237 Beatty Drive Sacramento, CA 95826



U.H.M.W. Skid Plate / Under Armor Package

<u>Ultra. High. Molecular. Weight. Polyethylene All Terrain Skid Plate / Under Armor Kit For UTV's</u>

Installation guide Can Am Maverick MAX (2013-2014)

Covers : DPS, XRS, And Turbo Models



Can Am Maverick Max (2013-2014)

Skid Plate Hardware





M6- 1.0 x 40mm Flange Bolt

Spacers · /---


Stock Hardware

Counter Sunk
<u>Washers</u>

MG- 1.0 x 20mm Thread Forming Bolts Re-Use
Stock Hardware
As Needed.
Skid plate will form to
chassis as bolts are
fastened securely.

A-Arm Hardware

14"- 20 Ny-Lock Nut



*Drilling Instructions: *

Use a: #Nº7 - OR- 13/64^{th"} drill bit and / or a ¼"- 20 Tap

(one size above the commonly available $3/16^{\rm th^{\prime\prime}}$ bit)

To drill and thread self tapping bolts in to chassis frame.

Finger Thread All Bolts Prior To Fastening Securely With Power Tools.

We strongly recommend the use of a "<u>Thread Locking Compound</u>" when installing any mounting hardware.

(When installation is complete, ensure all bolts are fastened securely.)

Can Am Maverick Max (2013-2014)

Re-Use All
Stock Hardware.
Finger Tighten All Bolts Before,
Fastening Bolts Securely.

⊗ = Drainage Holes Do Not Use For Mounting



Rear Skid Plate:

Install using : (2x) <u>Stacked Spacers,</u>
with (4x) <u>Stock Bolts</u> & <u>Washers</u>
(M6-1.0 x 20mm Thread Forming Bolts) in (#a) locations.



Main & Mid Skid Plate:

Install using : (20x) Stock Bolts & Washers

(M6-1.0 x 20mm Thread Forming Bolts) in (#a) locations.

Install mid skid Ist, main skid 2nd. Note tongue & groove.

Using: M6-1.0 x 40mm Flange Bolts

with M6-1.0 Flange Lock Nuts in (#b) locations.

(Disregard (#c) & (#d) locations in this step)



Front Diff. Skid Plate:

Install using : (4x) <u>Stock Bolts</u> & <u>Washers</u>
(<u>M6-1.0 x 20mm Thread Forming Bolts</u>) in (<u>#a</u>) locations.

Using : (2x) <u>M6- 1.0 x 40mm Flange Bolts</u>
with <u>M6- 1.0 Flange Lock Nuts</u> in (<u>#b</u>) locations.



Side Mounting Holes:

(See Drilling Instructions On Hardware Pg.2)
Once skid plates are aligned in place,
drill side mounting holes. Install:
(16x) ½"x 20"x ¾" Self Tapping Bolts in (#c) locations.
(2x) ½"x 20"x 1½" Self Tapping Bolts in (#d) locations,

Fasten All Bolts Securely



"D" Clamp A-Arm Guards:


Install : (4x) "D" clamps over a-arm tubing use :

(4x) ½"x 20"x 1" Counter Sunk Bolts

with (4x) ½"x 20" Ny-Lock Nuts, and (4x) Gold Washers

For each A-Arm Guard.

*Ensure Clearance For Turn Radius & Vertical
Travel Before Fastening Securely.



*A:1

A:1

A:1

