




# Truck Seats Service Kits




1718 South Concord Street  
Davenport, Iowa  
800-553-3013

# ATLAS II



SA18056


SA18131



SA35249 Boot


SA23780.901  
4" riser

SA18020




SA35173

SA35189 - RH pod



S20501.



SA18015

SA18197.

SEE NOTE 1

SEE NOTE 2

SA23511



## Service Parts - Atlas II Truck seats

### Atlas II Thermassage, DLX, PC Series

	Part #
<b>Suspension Service kits</b>	
Complete Atlas suspension Service Replacement w/slide/isolator	SA23511.901
Suspension slide/isolator replacement kit - Complete assembly	SA18197.901
Double locking slide service kit	SA18196.901
Slide Roller guide Service kit	SA23556.901
RH Spring slide lock Service kit	S20320.901
LH Spring slide lock Service kit	S20319.901
Suspension shock kit	SA18193.901
Suspension bumper/roller service kit	SA18195.901
Air spring service kit	S9383.901
Isolator Service kit	SA18015.901
Multi-plate Service kit	SA18020.901
Black vinyl suspension skirt kit	SA18151.2X2.901
Molded rubber suspension boot	SA35249.901
<b>Seat top Service kits</b>	
Contoured back frame structure	SA23748.901
Seat pan Service kit - <b>Thermassage, DLX</b>	SA17943.901
Seat pan Service kit - "PC"	SA18198.901
3 valve control housing w/valves LH - <b>DLX, PC</b>	SA35173.901
3 valve control housing w/valves LH - <b>Heat or Heat /Massage</b>	SA35716.901
2 valve control housing w/valves LH - <b>Heat / Ventilation</b>	SA35717.901
RH Atlas II Control pod - <b>all</b>	SA35189.901
Quad chamber air lumbar kit	S20501.901
Ind. 3-position seat extension kit - DLX	SA18056.901
Ind. 3-position seat tilt kit - DLX	SA18131.901
Integrated 3-position seat tilt Handle Kit - PC	SA23108.901
Back Recliner service kit	S31302.0901
<b>Armrest Service Kits</b>	
Armrest - pivot bar, bolt Service Kit	SA23396.901
Bezel - Atlas armrest (long) service kit	S20558.901
<b>Foam, Cushions &amp; Covers</b>	
<b>Call Sears/Atlas customer service for part numbers.</b>	
1-800-553-3013	