Grand Surfaces



PREVENTIVE CARE

- Protect floor during other works with craft paper, plywood, or hardboard.
- Recommended room conditions: 35-65% R.H. at 20°C (68°F).
- Use room humidifier during intensive room heating to prevent floor dryness and shrinkage.
- Rugs or mats on floor can increase surface temperature beyond recommended limit (20-22ºC).
- Avoid dragging furniture across the floor; use felt pads on chair and furniture legs.
- Office roller chairs must comply with EN12529 (Type W) and use protective office mats.
- Prevent moisture on the floor; use quality walk-off mats at entrances.
- Place rugs or mats in front of kitchen appliances and sink for protection against wear and spills.
- Expect color change in cork and wood due to natural light exposure; move rugs and furniture for even color change.
- Use blinds, curtains, or sun screening systems to minimize fading due to sunlight.
- Avoid latex or rubber backed mats as they can stain the floor permanently.
- Do not use cleaning products with abrasive ingredients or solvents (e.g., acetone).
- Avoid wire brushes for cleaning.
- Use mild detergent, vacuum cleaner, or broom handle with cloth for regular maintenance.
- Amorim WISE recommends specific maintenance products for optimal results; follow instructions on packaging and technical data sheets.

Grand Valley Tile

(519) 743-8300

info@grandvalleytile.com