



Number: GZHT90866801

Date: Feb 27, 2019

Applicant: CORTINA N.V.

MEERSBLOEM-MELDEN 42, 9700 OUDENAARDE,BELGIUM

Attn: PETER DE MEZURE

Sample Description:

Two (2) groups of submitted samples said to be:

(A) Three (3) pairs of Men's Injection pull on safety boots in Black.

(B) Four and a half (4.5) pairs of Steel plates.

Standard : ASTM F2413-18

Size : US 9

Buyer's Name : CORTINA N.V.
Ref. No : BESTBOOT2
Brand : SAFETYJOGGER
Manufacturer : CORTINA N.V.

Colour : BLACK
Vendor : -Supplier : -P.O. No. : --

Ref. : Men Casual High Safety with M1159 Mould Outsole

Country Of Origin : --

Goods Exported To : Belgium/U.S.A.

Date Received/Date Test Started: Feb. 02, 2019/Feb. 11, 2019

Date Final Information Confirmed: --

Test Result Please Refer To Attached Page(S).

Should you have any guery on this report, you may contact at gzfootwear@intertek.com

Authorized By:

For Intertek Testing Services Shenzhen Ltd.

Guangzhou Branch

Guiliang Dong Senior Lab Manager

Page 1 Of 4

CL / kayyu

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司 #01/E501/E601/E701/E801, 3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou

Room 02, 1-8/F. & Room 01, E101/E201/E301/E401/E501/E601/E701/E801, No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong, China 广州经济技术开发区科学城彩频路 7 号之二第 1—8 层 02 房、01 房 101、E201、E301、E401、E501、E601、E701、E801

China 中国广州经济技开发区开发大道 235 号恒运大厦 3 楼

Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730

Economic & Technological Development District, Guangzhou,







Number:

GZHT90866801

Total Quality. Assured. TEST REPORT

Tests Conducted (As Requested By The Applicant)

Protective Toe Impact Resistance (I) (ASTM F2412-18a, 5, Impact Force: 101.7 J (75 lbf), Testing Performed At 22℃ And 50% RH)

	(A)	ASTM F2413-18 Requirement	Pass / Fail
	Interior Height Clearance	 -	
Left:	18.1 mm	≥ 12.7 mm	Pass
Right:	19.0 mm	≥ 12.7 mm	Pass
Left:	18.5 mm	≥ 12.7 mm	Pass

2 Protective Toe Compression Resistance (C) (ASTM F2412-18a, 6, Compression Force: 11 121 N (2 500 lbf), Testing Performed At 22℃ And 50% RH)

	(A)	ASTM F2413-18	Pass/Fail
		<u>Requirement</u>	
	Interior Height Clearance		
Left:	19.7 mm	≥ 12.7 mm	Pass
Right:	20.0 mm	≥ 12.7 mm	Pass
Right:	19.2 mm	≥ 12.7 mm	Pass

3 Static Dissipative Footwear (SD) (ASTM F2412-18a, 10, Conditioned At 22°C And 50% RH For 24 h And Testing Performed At The Same Conditions.)

	(A)		ASTM F2413-18 Requirement	Pass/Fail
	Left	4.5 $ imes$ 10 $^6\Omega$	*	Pass
Sample 1	Right	$4.7 \times 10^{6}\Omega$	*	Pass
	One Pair	$3.7 imes 10^{6}\Omega$	*	Pass
	Left	$6.9 imes 10^{6}\Omega$	*	Pass
Sample 2	Right	$6.5 imes10^{6}\Omega$	*	Pass
	One Pair	$4.8 \times 10^{6}\Omega$	*	Pass
	Left	$9.7 imes 10^{6}\Omega$	*	Pass
Sample 3	Right	$4.8 imes 10^{6}\Omega$	*	Pass
	One Pair	$4.5 imes 10^6 \Omega$	*	Pass

Remark: * = SD 100 : $1 \times 10^6 \Omega \sim 1 \times 10^8 \Omega$

/ kayyu

Page 2 Of 4

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

Room 02, 1-8/F. & Room 01, E101/E201/E301/E401/E501/E601/E701/E801, No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong, China 广州经济技术开发区科学城彩频路 7 号之二第 1—8 层 02 房、01 房 101、E201、E301、E401、E501、E601、E701、E801

中国广州经济技开发区开发大道 235 号恒运大厦 3 楼

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou

中国)州经济技术及区并及人理 235 亏但运入厦 3 核 Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730

Economic & Technological Development District, Guangzhou,

Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663







Number:

GZHT90866801

Total Quality. Assured. TEST REPORT

Tests Conducted (As Requested By The Applicant)

4 Puncture Resistance Footwear (PR) (ASTM F2412-18a, 11, Conditioned At 22°C And 50% RH For 24 h And Testing Performed At The Same Conditions.)

	(B)	ASTM F2413-18 Requirement	Pass/Fail
Left:	The Test Pin Did Not Penetrate Beyond The Face Of The Material Nearest The	Min. 1 200 N (*)	Pass
Right:	Foot Before 1 200 N. The Test Pin Did Not Penetrate Beyond The Face Of The Material Nearest The Foot Before 1 200 N.	Min. 1 200 N (*)	Pass
Left:	The Test Pin Did Not Penetrate Beyond The Face Of The Material Nearest The Foot Before 1 200 N.	Min. 1 200 N (*)	Pass

Remark: * = The Test Pin Does Not Visually Penetrate Beyond The Face Of The Material Nearest The Foot.

5 Corrosion Resistance For Puncture Resistant Plates (ASTM F2412-18a, 11.8 & ASTM B117, 5% NaCl Solution For 24 Hours)

	(B)	ASTM F2413-18	Pass/Fail
		<u>Requirement</u>	
Left:	No Sign Of Corrosion.	*	Pass
Right:	No Sign Of Corrosion.	*	Pass
Right:	No Sign Of Corrosion.	*	Pass

Remark: * = No Sign Of Corrosion, De-lamination, Or Deterioration.

6 Flex Resistance For Puncture Resistant Devices (ASTM F2412-18a, 11.7 & CSA Z195-14, 6.3.2)

	(B)	ASTM F2413-18	Pass/Fail
		<u>Requirement</u>	
Left:	No Signs Of Cracking After 1.5 x 10^6	*	Pass
	Flexes.		
Right:	No Signs Of Cracking After 1.5 x 10^6	*	Pass
	Flexes.		
Left:	No Signs Of Cracking After 1.5 x 10 ⁶	*	Pass
	Flexes.	•	

Remark: * = No Signs Of De-lamination Of Layers Or Cracking After 1.5 x 10^6 Flexes.

/ kayyu

Page 3 Of 4

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

Room 02, 1-8/F. & Room 01, E101/E201/E301/E401/E501/E601/E701/E801, No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong, China 广州经济技术开发区科学城彩频路 7 号之二第 1—8 层 02 房、01 房 101、E201、E301、E401、E501、E601、E701、E801

中国广州经济技开发区开发大道 235 号恒运大厦 3 楼

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou

中国)州经济技术及区并及人理 235 亏但运入厦 3 核 Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730

Economic & Technological Development District, Guangzhou,





Number: GZHT90866801



End Of Report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. No copy of the test report(except for full text copy) shall be made without the written approval by Intertek.

/ kayyu

Page 4 Of 4

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

Room 02, 1-8/F. & Room 01, E101/E201/E301/E401/E501/E601/E701/E801, No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong, China 广州经济技术开发区科学城彩频路 7 号之二第 1—8 层 02 房、01 房 101、E201、E301、E401、E501、E601、E701、E801

unna 中国广州经济技开发区开发大道 235 号恒运大厦 3 楼

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou

中国)州经济技术及区并及人理 235 亏但运人复 3 核 Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730

Economic & Technological Development District, Guangzhou,

Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663