intertek

Total Quality. Assured. TEST REPORT



Date: Mar 25, 2019

Applicant:

CORTINA N.V. MEERSBLOEM-MELDEN 42, 9700 OUDENAARDE,BELGIUM Attn: PETER DE MEZURE

Sample Description:

Sample Description:							
	Two (2) groups of submitted samples said to be:						
	(A) Two (2) pairs of Men's Injection slip on occupational shoes in Black						
	(B) One (1) pair of Men's Injection slip on occupational shoes in Blue.						
	Standard :	ASTM F2892-18					
	Size :	US 9					
	Buyer's Name :	CORTINA N.V.					
	Ref. No :	OXYVA					
	Brand :	OXYPAS					
	Manufacturer :	CORTINA N.V.					
	Colour :	(A) Black (B) Blue					
	Vendor :						
	Supplier :						
	P.O. No. :						
	Ref. :	OXYPAS OXYVA ESD UNISEX PRF NURS CLOG With M1922 EVA sole					
	Country Of Origin :						
	Goods Exported To :	Belgium/U.S.A.					
	Date Received/Date Test Started:	Mar. 19, 2019					
	Date Final Information Confirmed						

Test Result Please Refer To Attached Page(S).

Should you have any query on this report, you may contact at gzfootwear@intertek.com

Authorized By: For Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

Guiliang Dong Senior Lab Manager



/ nicoleho

P

Page 1 Of 3

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司 Room 02, 1-8/F. & Room 01, E101/E201/E301/E401/E501/E601/E701/E801, 3/F., Hengyun B No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong, China 广州经济技术开发区科学城彩频路 7 号之二第 1-8 层 02 房、01 房 101、 E201、E301、E401、E501、E601、E701、E801 Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663 Tel: +86 20 839

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou Economic & Technological Development District, Guangzhou, China 中国广州经济技开发区开发大道 235 号恒运大厦 3 楼

le: 510663 Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730

intertek



Total Quality. Assured. <u>TEST REPORT</u> Tests Conducted (As Requested By The Applicant)

Static Dissipative Footwear (SD) (ASTM F2412-18a, 10, Conditioned At 22 $^{\circ}$ C And 50 % RH For 24 h And Testing Performed At The Same Conditions.)

(A)			ASTM F2892-18 Requirement	Pass/Fail
	Left	4.2 × 10 ⁷ Ω	*	Pass
Sample 1	Right	1.6 $ imes$ 10 7 Ω	*	Pass
	One Pair	1.5 $ imes$ 10 7 Ω	*	Pass
	Left	$3.0 \times 10^7 \Omega$	*	Pass
Sample 2	Right	1.6 $ imes$ 10 7 Ω	*	Pass
	One Pair	1.1 $ imes$ 10 7 Ω	*	Pass
	(B)		ASTM F2892-18 Requirement	Pass/Fail
	Left	2.6 × 10 ⁷ Ω	*	Pass
Sample 3	Right	6.2× 10 ⁶ Ω	*	Pass
	One Pair	$5.7 imes$ 10 6 Ω	*	Pass
Remark: * = Si	D 100 : 1×10 ⁶ Ω ~ 1	×10 ⁸ Ω		

/ nicoleho

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

 深圳天祥质量技术服务有限公司广州分公司

 Room 02, 1-8/F. & Room 01, E101/E201/E301/E401/E501/E601/E701/E801,
 3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou

 No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong, China
 3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou

 广州经济技术开发区科学城彩频路 7 号之二第 1-8 层 02 房、01 房 101、
 Economic & Technological Development District, Guangzhou,

 China
 中国广州经济技开发区开发大道 235 号恒运大厦 3 楼

 Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663
 Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730

Page 2 Of 3

intertek



Total Quality. Assured. <u>TEST REPORT</u> Tests Conducted (As Requested By The Applicant)



End Of Report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. No copy of the test report(except for full text copy) shall be made without the written approval by Intertek.

/ nicoleho

Intertek Testing Services Shenzhen Ltd. Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司 Room 02, 1-8/F. & Room 01, E101/E201/E301/E401/E501/E601/E701/E801, 3/F., Hengyun Bu No.7-2, Caipin Road, Guangzhou Science City, GETDD, Guangzhou, Guangdong, China 广州经济技术开发区科学城彩频路 7 号之二第 1-8 层 02 房、01 房 101、 E201、E301、E401、E501、E601、E701、E801 Tel: +86 208213 9001 Fax: +86 20 82089909 Postcode: 510663 Tel: +86 20 839

3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou Economic & Technological Development District, Guangzhou, China 中国广州经济技开发区开发大道 235 号恒运大厦 3 楼 Tel: +86 20 83966868 Fax: +86 20 82228169 Postcode: 510730

Page 3 Of 3