Portable Triple Screen Laptop Workstation

Package Contents





Product Overview Infographics

Rubber pads

Item 7








Please expand the screen to stretch to avoid scratching the shell

Quick Gulde

Step 1: Mount the monitor to the laptop. Stretch it to the size of the laptop screen through the stand part, and lock monitor in place. Then use the small stand to stabilize the whole setup.



Step 2: Connect the P2 to the laptop via the monitor's USB Type-C/HDMI port If your laptop has 2 USB Type-C ports.

Option 1: If your laptop can provide 5V/2A power through the USB Type-C port. Then only two USB Type-C to USB Type-C cables are needed to connect the P2 and the laptop's USB Type-C port. You need items 1 and 5.

Option 2: If your laptop cannot provide 5V/2A power through the USB Type-C port, or after connecting, the monitor has no signal/signal is unstable. You have to use a 5V/2A external power supply (adapter) to connect to the P2's USB Type-C port. For external power supply (adapter), it is not included in the package. You need item 1, 4 and 5.

If your laptop has only 1 USB Type-C, 1 HDMI port:

Option 3: Use an USB Type-C to USB Type-C cable to connect the P2 and the USB Type-C port of the laptop, and connect the USB Type-C to USB Type-A cable (item 4). Connect P2 USB Type-C port to laptop USB Type-A port, connect HDMI to HDMI cable from P2 HDMI port to laptop HDMI port. You need items 1, 4, 5 and item 6.


If your laptop has only 2 HDMI ports:

Option 4: You can use a USB Type-C to USB Type-A cable (item 4). Connect the P2 USB Type-C port to the laptop USB Type-A port, use an HDMI to HDMI cable to connect the P2 HDMI port to the laptop HDMI port, and repeat the above operation on the other side of the screen, You need items 1, 4 and 6.




Quick Guide





How to plug and unplug the data cable: You need to pinch the head of the data cable to plug and unplug the data cable as shown in the figure, otherwise the data cable will be damaged.



Warm tip:

- 1. Please ensure type-c data wire is connected well with device interface,
- This product supports whole function of type-c (charging and video), integrated one line. If screen cannot be powered on or restarted, please supply external power of 5V/2A.

For more detailed information, please check the manual of the product