



1-1 (8x8) X1

1-2 X1

1-3 X1

1-4 X1

1:1

0.15

0.32

1-5 X1 X1 X1

1-6 X1 X1 X2 X2

1-7 X1 X1

1-8 X1 X1

1-9 X1 X1 X1 X1 X1 X1

1-10 X1 X1 X2 X2

1-11 X2 X2

1-12 X2 X2 X1 X1

1-13 (2x4) X1 X2 X1 X2

1-14 X1 X1 X2 X2

1-15 X1 X2

1-16 X2 X1

1-17 X1 X1 X1 X1

1-18 X1 X3 X1

1-19 X1 X2 X2 X2

1-20 X1 X1 X3 X2

1-21 X1 X1 X1 X1

1-22 (6x8) X1

1-23 X5 X1

1-24 X1 X1 X1 X1 X1 X1

1-25 X1 X1 X1 X1

1-26 X2 X2

1-27 X1 X1 X1 X2

1-28 X2 X2 X1 X1

1-29 X2 X1 X1 X2

1-30 X1 X1 X1 X1 X1 X1

1-31 X2 X2 X1

1-32 X3 X2 X1 X1 X1

1-33 X1 X1 X1 X1

1-34 X1 X1 X1 X1 X1 X1

1-35 (6x8) X1 (1x8) X1

1-36 X3

1-37 X1 X1 X1 X3

1-38 X3 X1 X1

1-39 X1 X1 X2 X1 X1

1-40 X1 X1 X1

1-41 (2x4) X1 X2

1-42 X1 X1 X1 X1

1-43 X1 X1 X1 X1

1-44 X1 X2

1-45 X1 X1 X1 X2

1-46 X2 X3 X2

1-47 X2 X2 X1 X2

1-48 X1

1-49 X1 X1 X1 X1 X1 X1

1-50

1-51