



**TEKSON®**

**3D Tacho**



**QUICK  
START**

Detailed operating  
instructions are  
provided on the device.


[www.tekson.eu](http://www.tekson.eu)

[www.tekson.eu](http://www.tekson.eu)

## Install the battery:



## Card reading by 3D Tacho



## Connect 3D Tacho to a PC:

1. Connect the Mini USB cable to the 3D Tacho slot
2. Plug the other end of the cable into the USB port in your PC
3. The installation is automatic
4. In the PC the device is visible as a Removable Disk<sup>1</sup>



Caution! For proper operation of the device, the time on your computer must be set correctly.

## Tachographs reading by 3D Tacho

Insert the company/control/workshop card into an empty tachograph slot (1 or 2)

1. Connect 3D Tacho cable to the device (small plug)
2. Connect the other plug of the cable to the tachograph
3. Turn on the Read Mode by selecting the appropriate button on the device<sup>2</sup>



<sup>1</sup> After you connect to the computer, a complete 3D Tacho User Manual is available on the device disk.

<sup>2</sup> For a detailed description of the operating modes selected by buttons please refer to the User Manual.