

Windshield Defender™ NanoPax®

Application Instructions

Application Instructions:

- 1 Clean and dry the surface that is to be treated – the cleaner the surface, the better the coating.
- 2 Once thoroughly clean and dry, apply the Windshield Defender™ protective coating onto the surface using firm circular, overlapping motions, going over the entire area at least twice.
- 3 To test the application, spray the glass, and look for uniform water beads. For areas that are not beading up uniformly, dry the entire surface and reapply the Windshield Defender™ coating as needed.
- 4 Finalize the application process by polishing the glass with a microfiber towel. If preferred, you may wash the windshield with soapy water.

Important:

Do not apply the Windshield Defender™ coating in direct sunlight and do not unfold the towelette immediately upon removal of the package; only unfold as needed.

