## **GENUINE ACRYLIC VISOR**

## **INSTALLATION AND USER'S INSTRUCTIONS**

Thank you for purchasing a genuine Mazda accessory. Before removal and installation, be sure to thoroughly read these instructions.

Please read the contents of this bookler in order to properly install and use the acrylic visor.

## **⚠** WARNING

- There are several  $\ \triangle$  WARNING and  $\ \triangle$  CAUTION sections in this booklet concerning safety when installing or removing the acrylic visor. Always read and follow them in order to prevent injuries, accidents, and possible damage to the vehicle.
- $\triangle$  WARNING: Indicates a situation in which serious injury or death could result if the warning is ignored.

 $\triangle$  CAUTION: Indicates a situation in which bodily injury or damage to the vehicle could result if the caution is ignored.

- Do not modify the acrylic visor.
  Do not install the acrylic visor in any way other than described in the following instructions. If you have any questions about the use of the accessory, ask your Mazda dealer for proper advice before using it.
- Mazda and its suppliers are not responsible for injuries, accidents, and damage to persons and property that arise from the failure of the dealer or installer to follow these
- instructions. To ensure safety and reliability of the work, installation, removal and disposal work
- must be carried out by an Authorized Mazda Dealership.

  Be careful not to lose removed parts, and be sure that they are kept free from scratches, grease or other dirt.

PART NAME: ACRYLIC VISOR PART NUMBER: BHN1 V3 700 APPLICABLE MODEL: MAZDA3

### To the dealer

· Please turn over these instructions to the customer after installation.

### To the customer

- Keep these instructions after installation. The instructions may be necessary for installing other optional parts or removal of this accessory.
- · Should the vehicle or this accessory be resold, always leave these instructions with it for the next owner.

2. COMPONENTS

1. INSTALLATION VIEW

SEDAN

Verify that the kit includes all the following parts and that they are free of dirt, scratches, or damage.

This product can be shared by SEDAN and HATCHBACK.

натснваск

	PART	PART NAME	Qty		PART	PART NAME	Qty
1		Acrylic visor (Front RH)	1	2		Acrylic visor (Front LH)	1
3		Acrylic visor (Rear RH)	1	4		Acrylic visor (Rear LH)	1
5		Installation and user's instructions	1				

0

 $^{\star}$  The figure shows only the left side, however, the procedure is the same for the right side.

0

YP-44

YP-44

# 3. BEFORE INSTALLATION

1. REQUIRED TOOLS ☆ Hair dryer (Use when the temperature is low.)

**△ WARNING** Before performing work, park the vehicle on level ground, apply the parking brake secur-ely, and then block the wheels. If the wheel block is not set, the vehicle will move during the work, and it may cause injury.





## 4. Application of double-sided adhesive tape

\* Parts for installation indicate doors and bumpers where the acrylic visors are to be installed and the installation parts indicate new acrylic visors to replace old ones

## Avoid work in conditions where the temperature is 15°C or lower.

Adhesive strength is determined by the adhesive viscosity and resin softness. The lower the atmospheric temperature (ISC or lower), the lower the adhesive viscosity and resin softness. The lower the adhesive strength, the control of the adhesive strength. For this reason, avoid work in conditions where temperatures are 15°C or lower. When working under this condition is inevitable, warm both the parts for installation and the installation parts.

2. Press the adhesive tape evenly

Press the adhesive tape to the parts for installation evenly to maintain sufficient adhesive strength. Areas at the ends of the adhesive tape and curved surfaces of the parts for installation require particular attention.

3. Keep surface of parts for installation clean

If dirf. dust, or oil are present on the surface of the parts for installation, the adhesive strength of the adhesive tape will be diminished. Wipe clean any dirt, dust or oil from the surface of the parts for installation beforehand. Clean interior parts with IPA (sopropyl alcohol exterior parts with IPA (sopropyl alcohol exterior parts with IPA (sopropyl alcohol).







clean.

Do not touch the adhesive tape surface with hands. This will cause oil from the skin to be transferred to the adhesive tape, diminishing the adhesive tape, diminishing the adhesive strength of the tape. Touching the adhesive tape surface with work gloves should also be avoided since this may transfer dust or dirt particles to the surface of the athesive tape.

## 5. Post-installation handling

Leave the vehicle for 24 hours after work is completed to allow the tape to sufficiently adhere to the parts. Do not drive or wash the vehicle during this period, Also, do not leave vehicle outside if it is raining. Doing so will adversely affect achesive strength of the adhesive tape. The adhesive strength of the adhesive tape. The adhesive force will greatly deteriorate if the installed and vision and therefore must be avoided.






## 5. PREPARATION FOR ACRYLIC VISOR INSTALLATION

. The figure shows only the left side, however, the procedure is the same for the right side.

- 1. Roll down all the front and rear door glasses.
  2. Degrease, clean (with IPA), and completely dry the sash molding and the B pillar garnish (shaded areas in figure) before installing the acrylic visors.



1. Peel the adhesive tape backing 20-30mm as shown in the figure below and fold them outward.



Do not peel the adhesive tape backings more than 30mm, as this will make it impossible to move the acrylic visors when positioning them correctly.

Before installation

## **6. ACRYLIC VISOR TEMPORARY INSTALLATION**

### Acrylic visor temporary installation <Front>


- Acrylic visor temporary installation \*\*Torion\*\*

  I. While holding the bracket with your fingers, push bracket onto edge of door glass channel.

  Then fit the mounting bracket in the sash molding from the part A and then B in sequence carefully so that the sash molding lip is not caught on the bracket. (Do not fix them temporarily yet.)

  2. Insert the acrylic visor front end bracket (at the part C) into the Sail garnish fully until it stops.

  Align the upper end of the acrylic visor with the sash molding R end.
- 3. Temporarily install the acrylic visor (front) with its upper part (part D) aligned with the sash molding R end




### Acrylic visor temporary installation <Rear>

- While holding the bracket with your fingers, push bracket onto edge of door glass channel.
   Then fit the mounting bracket in the sash molding from the part E and then F carefully so that the sash molding lip is not caught on the bracket. (Do not fix them temporarily yet.)

  2. Align the upper end of the acrylic visor rear (at the part G) with the sash molding R end, and then align its lower end with the rear end gap (1.0 mm to 5.0 mm) of the acrylic visor front.

  3. Align the upper end of the acrylic visor rear (at the part H) with the sash molding R end, make sure that the rear end lines up with outer edge, and then fix the part G and H temporarily.



## 7. ACRYLIC VISOR INSTALLATION

## Acrylic visor attachment


- . Before attaching the acrylic visors, perform the following check in the order shown Are the acrylic visors correctly positioned with reference to the sash molding and the B pillar garnish?
   Are the brackets correctly placed?
   Is there no interference of the acrylic visors with the door opening or closing?

- ★ If any problem is found in the above check, reposition the acrylic visors.
   ★ When there is no problem in the above check 1 to 3, align the acrylic visor upper parts with the sash molding R end, and remove the adhesive tape backings (a little of the tape ends should be peeled off beforehand) in direction of the arrows, being careful not to twist them. Then press down the acrylic visors evenly to completely affix them to vehicle body.


-5-

## NOTE

- Press down evenly on the acrylic visors where the double-sided adhesive tapes are attached with 49N or more force applied (to the extent vehicle rocks). If adhesive strength of the 
  area is insufficient, this will result in partial floating and cause water seepage and wind noise.
   Adhesive strength of the double-sided adhesive tape will deteriorate if an installed visor is removed and re-installed again and therefore must be avoided.



## Checking the door glass channel 1. Press the door glass channel with your fingertips to conform it to the brackets.




-6-

YP-44

YP-44

Always check that there is no problem in the door glass channel, otherwise the door glass operation
may malfunction and/or water leakage will result.

- 1. Inspect all the affixing surfaces from the top and bottom to make sure that no part of the acrylic visor has lifted.
- Lightly pull the acrylic visors to make sure that they are securely affixed.
   Make sure that the sash molding lips are not caught on the brackets.
   Make sure that there is no nipping of the door glass channel or noise by raising and lowering the door glass.



## - To our customers -

- If the Acrylic visors get dirty, wipe it lightly with a clean rag dampened in a neutral detergert.
   (Do not use thinner, benzene, gasoline or any organic solvent. It may cause deformation or discoloration to the plastic.)
- When washing your vehicle using car wash machines or high-pressured washers, avoid excessive force to the acrylic visors to prevent them from detaching from the vehicle body.

Consult your Mazda Dealer if you have any questions regarding this accessory.

Date			(ye	(year/month/day):	
VIN No.					
Approved		Checked		Prepared	

Installation	MAZDA3	ACRYLIC VISOR
inspection sheet		BHN1 V3 700

Please check for the following items.

1. Inspection items after installation.	
Inspect the installed parts and uninstalled parts fit & finish and scratch, stain.	

# 2. Restoration of vehicle parts inspection.

Section to be inspected	Inspection items	Content inspection	CHECK
Door glass channel	Fitting	·Check that the fitting of the door sash, whether it is restored.	
Power window auto function	Function	<ul> <li>Check that the auto functionality of the driver's power window.</li> <li>Check that the operation of all power window.</li> <li>Check that the automatic reversing function does not work.</li> </ul>	

# 3. Verifying the installation of the visor and the operation confirmation.

		•	
Section to be inspected	Inspection items	Content inspection (Interior and exterior parts)	CHECK
Acrylic visor	Loose	·Check that the mounting portion has not loosened.	