
AR Marker



Application

This code is used for AR calibration. After calibration, virtual elements will be spatially aligned with the real-world environment.

Process

Please stick the calibration code on the wall at horizontal eye level and after putting on your glasses, go to "Settings-Display Settings-AR Calibration" to finish the calibration.

i Precautions

Please keep the calibration code flat, and the side length of the black calibration code is 6cm.