



# Great MINI

Revolutionary BIOSKIN material  
As Close To The Human Skin



Press ON/OFF and hold for two seconds



ON/OFF changes the modes of vibration



EN

Powerful motor

Press ON/OFF (⏻) and hold for two seconds.

(⏻) ON/OFF changes the modes of vibration

DE

Ein leistungsfähiger Motor

Für die Entsicherung drücke ON/OFF (⏻) und halte den Knopf für zwei Sekunden lang gedrückt.

(⏻) ON /OFF Ändern der Vibrationsmodi

FR

Moteur puissant

Appuyez sur ON/OFF (⏻) et maintenez la touche enfoncée pendant deux secondes.

(⏻) ON /OFF change les modes de vibration

ES

Motor potente

Pulse ON/OFF (⏻) y mantenga pulsado durante 2 segundos.

(⏻) ON/OFF cambio de modos de vibración

RU


Сильный мотор

Нажмите ON/OFF (⏻) и удерживайте 2 секунды. для включения.

(⏻) Кнопка ON/OFF переключение режимов вибрации

## Remote control of Gring XL


Great MINI can be controlled remotely by a no-cord controller – the Gring XL (sold separately). The controller fits a finger perfectly enabling an easy switch to a different mode while you enjoy the Great MINI.



● ON/ increasing the vibration



● Modes of vibration



● Decreasing the vibration / OFF

## CHARGING

Connect the charger to the points of charging at the bottom of the toy. The USB-end is connected to the USB port of your computer or adaptor. When charging a light indicator starts blinking. As soon as the toy is fully charged the light stops blinking. The buttons will not work when charging meaning you can't use the toy.

- When the battery is low Great MINI will switch modes automatically to switch off.
- Charging time is around 1.5 hours. After charged fully the toy runs about 40 minutes at max speed.

**3-YEAR WARRANTY**