

DOA Colour

Component Sorting Sheet

For the full, step-by-step assembly guide, visit
diy.re/doa-manual


1

&


4

Resistors


R1, R2, R5
68R




R3
150R




R4
47k



R6
10k




R7
2k or 4.7k




R8
390R



R9
82R or 200R




B, R
220k



2

Capacitors

C1, C2
100uF caps



C3
10uF caps



C4, C5
100pF ceramic cap



C6
470uF cap



3

Connectors

U1
DOA sockets



CON1
8-pin header



Snap-in standoffs

