

Mojo Maestro Colour

Component Sorting Sheet

For the full, step-by-step assembly guide, visit diy.re/mojo-maestro-manual

1

Connectors


IC1
IC socket



CON1
8-pin header



Snap-in standoffs



2

Resistors

R1, R6, R7 10k	R2 1k	R3 1.6k	R4 150R	R5 22k	R 47k	B 330k
brown black black red brown	brown black black brown brown	brown gray black brown brown	brown green black black brown	red red black red brown	yellow purple black red brown	orange orange black orange brown

3

Caps, Diodes, and Headers

C1
.039uF film cap




C2
100uF electrolytic cap



CB1, CB2
.1uF ceramic caps



D1, D2
1N34 diodes



CON2
3-pin header



CON3
6-pin header



CON2, CON3
Shunts



4

Integrated Circuit

IC1
qDual opamp

